


From above



104 cogs on spur gear

108 cogs on bevel ring




Fig 3.13 Wicken Windmill: Spur Gear