

| DATE | PLACE | NAME | WORK | PAGE |
|----------|-------------------|------------------|---|--------|
| 19.10.89 | Swarden | Cornes | Neck brass for windshaft diagram | C1 |
| 19.10.89 | Hoath farm | Manted? | 15 sheep troughs | C1 |
| 17.10.89 | Smeeth watermill | | Brasses, bearings, teeth, gates | C2 |
| 17.10.89 | | Collard | Cheps? For drill | C2 |
| 17.10.89 | Challock | George Small | Peak stones | C2 |
| 17.10.89 | Minster | Packer | Peak stones | C3 |
| 25.10.89 | Blean Old & New | | Brasses, wire, wooden odds dimensions | C3 |
| 25.10.89 | Martin mill | Myles | Sweeps/repairs measurements | C4 |
| 25.10.89 | Ramsgate Queen St | Wotton | Repairs in brewery | C5/6 |
| 19.11.89 | Sturry Court | Chapman | Speed of chaff cutter | C7 |
| 19.11.89 | | Butcher & Stokes | Bearings shutters for mill | C7 |
| 19.11.89 | Martin mill | Myles | Sweeps measurements | C8 |
| 19.11.89 | Preston mill | Solley | Girders sizes and location | C9/10 |
| 19.11.89 | Dover | Chitty | Rings | C10 |
| 16.11.89 | Thanet | Hogben | Sizes new spur wheel | C11 |
| 7.12.89 | Ramsgate brewery | Tomson & Wotton | Repairs to engine bearings/shafts | C12/13 |
| 7.12.89 | | Flint & Sons | Chamber for wort pumps | C14 |
| | Sewage works | | Nipples, bend, asbestos cock, handle | C15 |
| | Chilham | | Straps and fasteners | C15 |
| 11.12.89 | Preston mill | Dunn | Stones, frame, bearings, lay shaft, gears, wood | C16 |
| 18.1.90 | Elham | G Ellen | Turnip cutter | C15 |
| 16.1.90 | Adisham mill | Jarvis | Hoop for curb. Cap repairs | C17 |
| | Selling | F Neame | Repairs upright shaft | C17 |
| | | Baldock | Piston rings | C18 |

| | | | | |
|---------|------------------------|-------------------|---|-----|
| 29.1.90 | Charing mill | Pay | Sweep, cants, posts repairs | C19 |
| 01.2.90 | Cannon B H | Tomson & Wotton | Pulley, belting | C20 |
| 11.2.90 | Mersham | Messrs Cornes | Silk | C20 |
| | Northbourne mill | Fuller | Steam nut | C20 |
| | Barton mill | Kingsford | Tuns. Horsing. | C21 |
| | Smeeth | Gasston | Pulley | C21 |
| | | Gillett | Bush for wheel | C21 |
| 9.4.90 | | Baldock | Bush for link motion diagram | C22 |
| | Boughton mill | Miles | Shaft for steam tackle | C23 |
| | | Drury | Price for dressed stone | C23 |
| | Bursted | Capt Vaughan | Frame for well | C24 |
| | St Mildreds brewery | Messrs Williamson | Drum. Bearings. Ring | C25 |
| | | White | Peak stone price | C26 |
| | | Sladden | Felloes for wagon wheel | C26 |
| | Sandwich mill | Harvey | Sack hoist sizes | C27 |
| | Preston mill | Dunn | Gandy belt . | C28 |
| | | Swinford | Horse rake list | C28 |
| | | Andrews | Mower hire | C28 |
| | | Hancock | Stone nut size | C28 |
| 7.7.90 | Bridge mill | | Cogs for brake wheel, wedges etc | C28 |
| 11.7.90 | Stodmarsh mill | | Repairs sizes | C29 |
| 11.7.90 | Folkestone | Corporation | Repairs to roller, fire box overhall engine | C30 |
| 16.7.90 | Pluckley mill | A J Burrows | Midling, canister, sweeps | C31 |

| | | | | |
|---------|-------------------|-----------------------|---|--------|
| 20.7.90 | | Albert Curling | Fire bars | C32 |
| 28.7.90 | Chartham | Vaughan | Marking iron for sheep | C32 |
| 30.7.90 | Adisham mill | Jarvis | Stone pinion sizes | C32 |
| | | Smith | Brand iron for sheep | C32 |
| | Sturry | Chapman | Matchless 4 arm reaper | C32 |
| 4.8.90 | Wingham mill | Maplesden | Plates to top of curb diagram | C33 |
| | Chilham | Exors of Peter Martin | Truck wheel arm | C33 |
| 16.8.90 | Brenzett | T Nash | Peak stone price to Appledore | C34 |
| | Sandwich | Harvey | Step brass | C34 |
| | New Romney mill | | Midling stays, lead to balance sweeps | C34 |
| | Littlebourne mill | Smmith | New tuns, horsing, Brasses, Bevil wheel. Bridge | C35 |
| 8.9.90 | Wickham | Messrs Rudd & Walter | Pulley | C36 |
| 8.9.90 | Selsted | Hambrook | Shaft, blocks, pulleys for grind mill | C36 |
| 16.9.90 | Smarden mill | Cornes | Midling, sweep sizes | C37/8 |
| 16.9.90 | Preston mill | Dunn | Pumps for well diagram | C39/40 |
| 18.9.90 | | Messrs Weston & Allen | Water wheel buckets | C41 |
| 22.9.90 | Chilham | H. Gillett | Flour mixer. Screws. Pulley | C41 |
| 23.9.90 | Sandwich mill | M. Larkin | Sack tackle repairs diagram | C42 |
| 26.9.90 | Eastry mill | W. Clark | Steam tackle gears. Neck brass diagram | C43 |
| 1.10.90 | Deal | English | Cheek pieces | C44 |
| 2.10.90 | Waltham mill | Cloke | Cheeks size. Tail bearing diagram | C44 |
| | | Davison | Price new felloes | C44 |

| | | | | |
|----------|--------------------------|-----------------------|---|--------|
| 20.10.90 | Ramsgate mill | Messrs Hogben | Bevil for bruising mill. Shafting. Step brass sizes | C45 |
| | Barton Farm Dover | Bailey | Corn crusher. Pulleys | C45 |
| 24.10.90 | Deal mill | M English | Curb repair diagram | C46 |
| 25.10.90 | Horton Chapel | Corrie | Sold plough | C47 |
| 6.11.90 | Read mill | White | Sweep repairs sizes. Time 1 man & mate 1 week | C47 |
| 25.11.90 | Elham mill | Sutton | Midling | C48 |
| | Sandwich | Harvey | Joist measures | C48 |
| 12.11.90 | | Owen | Van body measures and diagrams | C49/50 |
| 28.11.90 | Barton mill | Kingsford | Wheat/flour machine repairs | C51 |
| 29.11.90 | Read mill | White | Windshaft bearing | C51 |
| 29.11.90 | Birchington mill | C. Hudson | Stone spindle diagram | C52 |
| 1.12.90 | | Edwin Neame | Wood shape | C52 |
| | Boughton | Richardson | Shafting | C53 |
| | Petham Court Farm | R. E. Thomson | Pulley for oil cake mill/horse wheel | C53 |
| 2.12.90 | | Messrs Weston & Allen | Step bearing for upright shaft | C54 |
| | Winterage Farm Acrise | May | Turnip cutter | C54 |
| | Yorkletts | Curling | Bearings | C55 |
| 19.12.90 | Acrise | May | Midling | C55 |
| 29.10.90 | Walmer | Page | Pulley | C55 |
| 1.1.91 | Northbourne mill | T. Fuller | Midling sizes | C56 |
| | Sandwich | Harvey | Shafting | C56 |
| | Dover | Bailey | Slide valve for Aveling | C56 |

| | | | | |
|---------|--------------------|----------------|---|--------|
| 9.1.91 | | Wacher | Belts | C57 |
| 20.1.91 | Chartham | Gillett | Beech timber | C57 |
| 29.1.91 | Whitstable mill | Feakiins | Cogs for steam gear | C57 |
| | | Mascall | Cogs for bevil pinion | C58 |
| | | Paul | Diagram spur pinion cog | C58 |
| | | Peters & Davis | Saw spiondle | C58 |
| 18.2.91 | Preston mill | Solly | Flour machine parts | C60 |
| 4.3.91 | Nonington mill | Messrs Harvey | Step bearing. Bearings for linseed mill | C61 |
| 7.3.91 | Preston mill | Solly | Step brass for wheat stones sizes | C62 |
| 13.3.91 | Eastry mill | W. Clark | Bridge for flour machine. Bearings | C62 |
| 17.3.91 | Sellinge | Sutton | Boring cylinder heads on plough engine | C63 |
| | | Kettke | Send price of horse rakes | C63 |
| | Herne Bay | Thomas Morris | Gandly belt for brickmaker | C63 |
| | Herne Bay | AShenden | Horse hoe | C63 |
| 13.3.91 | Herne | Swinford | Buy/sell portable engine | C64 |
| 23.4.91 | Selsted | Hambrook | Nuts, rivets | C64 |
| 28.4.91 | Wye | Kennett | Silk for centrifugal | C64 |
| | | | Fire devil sizes ands diiagram | C65 |
| 25.5.91 | Preston | Dunn | Pulley for chaff cutter | C65 |
| | | Hammond | Fittings for Howard mower | C66 |
| | Vale mill Guernsey | Hocart | Sweep & fan gear repairs. Diagram for new windshaft | C67/68 |
| | Vale mill Guernsey | Hocart | Fan flies diagram. Numbers of cogs in all gears | C69/70 |
| | Preston Old mill | | Numbers of cogs | C70 |

| | | | | |
|---------|----------------------|----------------|--|-----|
| 5.6.91 | | Corne | Pinion for Hornsby | C71 |
| 11.6.91 | | | Sargeant oak prices | C71 |
| 16.6.91 | Littlebourne | Messrs Savage | Traction engine fire box | C71 |
| | Stelling Minnis mill | Davison | Repairs to sweeps sizes | C72 |
| 16.6.91 | Herne Hill | A.Curling | Bushes, wheels, flanges | C73 |
| | Cheriton mill | | Alter common sweeps to spring | C73 |
| 1.7.91 | Ash | Marshall | Oak and tackle | C74 |
| 8.7.91 | Sandwich mill | Harvey | Brushes, wire for smutter. Pulley, fan spindle | C74 |
| | | Ind | Sweeps from Feakins sizes | C75 |
| | Willesborough | Messrs Cornes? | Sizes sweep rod | C75 |
| | | G. Mount | Repairs to Dover Lane oast | C76 |
| 6.8.91 | Chislett Park | Wilks | Repairs to sack roll bridge diagram | C77 |
| | Grove Bridge | Sutton | Cylinder boring | C78 |
| 1.9.91 | Egerton mill | Millgate | New middling | C78 |
| | | Callingham | Spanner for stone box. Guide staple for sweeps | C78 |
| 19.8.91 | Eastry mill | Clark | Brasses | C78 |
| | | Gambrill | Boiler tubes | C79 |
| 2.9.91 | Uphill mill | Kettle | Midling | C79 |
| | | Hocart | Collars. Cleats. Brushes. Beaters | C80 |
| | Guernsey mill | | Measurements inside mill | C81 |
| | Willesborough mill | Messrs Cornes | Measure and diagram of sweep | C82 |
| | Egerton mill | Millgate | Midlingv measures Paint & repair sweeps | C83 |
| | | Collard | Front to smoke box | C83 |
| | Margate mill | Ind | Striking chains. Neck brass | C83 |

| | | | | |
|----------|---------------------|----------------|---|--------|
| | Eastry | Clark | Repairs to worm gear | C84 |
| | Ramsgate | Hogben | Worm | C84 |
| | Thanet mill | Mrs Hogben | Bruising mill alterations | C85 |
| 4.10.91 | | Ind | Size of iron tooth for spur wheel | C86 |
| | Littlebourne mill | Smith | Neck brasses. Drive box. Tuns | C86 |
| | Ashford | Peters & Davis | Fire box repairs | C87 |
| | Ickham mill | Atkins | Waterwheel bearing | C87 |
| | Egerton mill | | Collar plate. Sweep repairs diagrams | C88 |
| | Whitstable Gas Comp | | Want force pump | C89 |
| | Graystone | Callingham | New sweep sizes | C89 |
| | Egerton mill | | Wedges | C90 |
| | Sutton Valence mill | Ward | Tail bearing diagram. Cheek pieces | C91 |
| | | Flint & Sons | Feed pipe to boiler | C92 |
| 9.11.91 | Thanet mill | Mrs Hogben | Engine repairs. Roofing. Spanner | C93 |
| 9.11.91 | Aldington mill | Gasston | Elevators | C94 |
| 17.11.91 | Brenzett mill | Nash | Midling. Cheek piece diagram. Other sweep repairs | C95/96 |
| 19.11.91 | Read mill | White | Shutters measures, Uplong, bars | C96 |
| 20.11.91 | Smarden mill | Buss | New outer midling sizes | C97 |
| 20.11.91 | Lympne mill | | Repairs curb, sweeps, upright shaft, geras | C97 |
| 24.11.91 | Adisham mill | Jarvis | Shutters sizes | C98 |
| | Smarden mill | Buss | Bolts, staples, bars | C98 |
| 19.11.91 | Herne mill | Wacher | Engine chimney. Bearings | C99 |
| 19.11.91 | Chislett mill | Wooton | Splice sweep rod. Shutters | C99 |

| | | | | |
|----------|-----------------------|-----------------|--|------|
| 28.11.91 | Sandwich mill | Harvey | Conveyer. Shafting. Plummer blocks | C100 |
| § | | H Gambrill | Beaters. Bolts. Plates for engine wheels | C101 |
| | | B.H. Flint | Bore cylinder of Yeast? engine | C101 |
| | | Messrs Petley | Sign board | C101 |
| | Newchurch mill | | Bevil for fan gear & repairs sizes | C102 |
| | Wye watermill | Kennett | Peak stone. Silk. Cogs on wheel | C102 |
| 11.12.91 | Faversham brick field | Rigden | Pins for elevator chain | C103 |
| | Sandwich | Harvey | Pulley | C103 |
| 15.12.91 | Ashford | Brown | Flange joint for feed pipes. Bushes | C103 |
| | Charing | Hicks | Price of Peak stones | C103 |
| 6.1.92 | Sandwich | Harvey | Chimney | C104 |
| | Lydd mill | Goble | Outer middling sizes. Cheek pieces diagram | C104 |
| 9.1.92 | Ramsgate | Mascall | Peak stone | C105 |
| 12.1.92 | Lydd mill | Goble | Wedges. Backstays. Board | C105 |
| | Northbourne mill | Fuller | Fire bars for Robey engine diagram | C105 |
| 27.1.92 | Sarre | Steddy | Peak runner | C106 |
| | | Price | Ironmonger. Bearings | C106 |
| | | Sladden | Bearings for shaker shaft | C106 |
| | | Gaskin | Bolts | C107 |
| | Whitstable | Callingham | Wheels for wagon | C107 |
| | St Laurence | Mascall | Tackle for driving chaff cutter | C109 |
| | Barton mill | Kingsford | Waterwheel buckets sizes | C109 |
| | Ramsgate brewery | Tomson & Wotton | Gearing. Shafting | C110 |
| | | B. H. Cannon | Back for refrigerator. Cups for wort pumps | C110 |

| | | | | |
|---------|-----------------|----------------|---|----------|
| 14.5.92 | Adisham mill | Jarvis | Neck brass. Step brass | C111 |
| | | | Measure of straps on Colshup? Machine Marshalls | C112 |
| | Chislett mill | M Wootton | Sweep measurements. Peak stone. Spur cogs | C113/114 |
| | Wye mill | | Sweep sizes | C114 |
| | | Bligh Bros | Water engine | C115 |
| | Quex farm | | Pulleys. Shafting to various machinery | C115/116 |
| 16.6.92 | Knowlton | | Offer to buy oak | C116 |
| 24.5.92 | | Johnson & Co | Quote for pumping | C117 |
| 30.5.92 | Petham | H Gambrill | Outer midlings size. Tail bearing | C117 |
| 9.5.92 | Barton mill | Kingsford | Bearings for centrifugal. Perforated steel for sieves | C118 |
| | Wingham | Maplesden | Bevil for steam tackle. Clutch coupling | C118 |
| 6.6.92 | Tilmanstone | Sir E B Rice | Repairs to Marshall engine. Howards reaper for repair | C119 |
| 10.6.92 | Barham mill | Walter | Outer middling size | C119 |
| 21.6.92 | | Peters & Davis | Pulleys | C120 |
| 22.6.92 | Nonington mill | Messrs Harvey | Gudgeons. Spindle to sieve | C120 |
| | Stelling Minnis | Davison | Sweeps sizes | C121/122 |
| 21.7.92 | Whitfield mill | Mummery | Stone pinion sizes. Water tank | C122 |
| 3.8.92 | Preston mill | Mrs Solly | Wood. Screws | C122 |
| | Adisham mill | | Sweeps sizes | C123 |

| | | | | |
|---------|------------------|----------------|--|----------|
| 3.8.92 | Preston mill | Mrs Solly | Head bearings for barley stone quant. Diagram | C123 |
| | Thanet mill | Mrs Hogben | Sweep sizes and diagram | C124/125 |
| 2.8.92 | Sutton Valence | | New sweeps sizes. Diagrams | C125/126 |
| 8.8.92 | Broadstairs mill | | Sweep sizes | C127/128 |
| 29.8.92 | | Ellis Laurance | Shaft. Collars. Blocks. Pulleys | C128 |
| 29.8.92 | Wye | Kenneth | Step brass. Brushes | C128 |
| 1.9.92 | Preston mill | Dunn | Spur wheel cog. Lard oil | C129 |
| | | Mrs Solly | Sweep sizes and diagrams | C129/130 |
| | Brook mill | Cook | Midling sizes | C131 |
| 20.9.92 | Ashford mill | Pledge | Peak stns. Sizes bed stone. Hopper. Pulleys for beanmill | C131/132 |
| | Egerton | Millgate | Chaff knives | C132 |
| | Smarden mill | Cornes | Peak runner | C132 |
| | Worth mill | Billing | Smutter. Pulleys Posts | C133 |
| | Hoath mill | Taylor | Neck brass and carriage | C133 |
| | | Earl Cowper | Pair cart wheels | C133 |
| | Blean | Messrs Tilden | Shoes on wheel | C134 |
| | Kingsnorth mill | | Corner post . Battens. Neck brass | C134 |
| | | Crundall | Deal price | C134 |
| | | Minster | Fly wheel for Bobby screen | C135 |
| | Sheldwich | Cobb | Measures of machine straps | C135 |

| | | | | |
|----------|-------------------------|-----------------|---|----------|
| 5.11.92 | Elham | White | Chaff cutter. Grindstone | C136 |
| | Wye mill | Kenneth | Peak runner | C136 |
| | Lenham Heath mill | Ganton | Sweep repairs sizes | C136/137 |
| | Uphill mill | Kettle | Gear for drivinf oat mill | C137 |
| | Worth mill | Billing | Dimensions silk reel | C138 |
| | Cannon brewery | Tomson & Wotton | New wood hop back. Diagram | C138 |
| 23.11.92 | | H. Gambrill | Peak runner | C139 |
| | | B. H. Cannon | Bevil wheel | C139 |
| | Ashford watermill | Pledge | Curbing sizes. Bearing for bean mill. Stone spindle | C141 |
| 29.11.92 | Ashford watermill | Pledge | Sack hoist for roller mill | C142 |
| | Kingsnorth mill | | Sash | C143 |
| | | Maplesden | Joists. Flooring. Jack | C143 |
| | | Callingham | New sweeps measures | C144/145 |
| | | Maplesden | Steel cover for smutter sizes and diagram | C145 |
| | Ashford | Peters & Davis | Engine overhaul | C146 |
| 14.2.93 | Sandwich mill | Larkin | Bevil for fan gear sizes | C146 |
| | Horton Chapel watermill | Carrie | Brasses for wheel. Bearings. Pinion | C147 |
| 17.4.93 | Margate mill | Coleman | Shaft. Couplings. Drive chaff cutter | C147/148 |
| | Bekesbourne | Jarvis | Crusher for oats, wheat, barley. Pulleys. Lay shaft | C148 |

| | | | | |
|----------|-----------------|----------|---|----------|
| 2.5.93 | Kennington mill | | Screws | C148 |
| 2.5.93 | Brook mill | | Midling size. Sweep repairs. Canvass sails size | C148/149 |
| 9.5.93 | Kennington mill | Stanley | Rubber for water gate. Tuns. Chain blocks | C150 |
| 20.5.93 | Read mill | | Sweep measures diagrams | C151/152 |
| | Guilton mill | Marshall | Brake wheel repairs | C153/154 |
| 29.5.93 | Adisham | Sladden | Wheels for wagon | C154 |
| | Lyminge | Rolfe | Step brasses.. Jack stick. Tables & trestles | C155 |
| | Chislett mill | Wootton | Stone nut sizes | C156 |
| | Ashford | Brown | Stud for slide gland | C156 |
| | | Morins | Knife for reaper | C156 |
| 29.6.93 | Elham Valley | Brick Co | Repairs to portable engine | C157 |
| | Eastry mill | W Clark | Upright shaft. Spur wheel sizees | C158 |
| | Laundry | Ellis | Pinion for ironing machine | C159 |
| 0.7.93 | Eastry mill | T Clark | Peak stones | C159 |
| | Nonington mill | Dilnott | Millstone | C159 |
| | Worth | Billing | Runner stone | C159 |
| | | | Stones I stock | C159 |
| | Herne | Swinford | Repairs to machine gear | C160 |
| | Stourmouth | White | Pulley. Ash sides | C160 |
| §12.7.93 | Herne Bay mill | Morris | Pump drive. Wood. Screws | C161 |
| | Kennington mill | Stanley | Peak stone | C161 |
| | Margate | Coleman | Elevator and pulley, straps and buckets Diagram | C161 |

| | | | | |
|-----------|--------------------|-----------------|--|----------|
| | | Williamson§ | Bevil wheels | C162 |
| | Sandwich mill | Larkin | Neck brass and block diagram | C163 |
| | Guilton mill | Marshall | Neck brass. Shutters. Lifts. Collar plate diagram | C164 |
| 0.9.83 | Guernsey | Hocart | Shutters sizes | C165 |
| | | Dunn | Dimensions fire bars diagram | C165 |
| | | Tomson & Wotton | Brasses for hop shaft | C166 |
| | Selsted | Hambrook | Shaft & pulleys | C166 |
| | Sutton Valence | Ward | Flooring. Hatches | C167 |
| | Brook watermill | | Cogs for pit wheel | C167/168 |
| | Tyler Hill | Whiteman | Horse gear. Chaff cutter repairs. Grist mill repairs | C168 |
| 0.10.93 | Deanes mill | Hooker | Repairs to van | C169 |
| 31.10.93 | Kenardington Place | H Gillott | Horse gear and chaff cutter | C169 |
| | Newchurch mill | Waddell | §Tailbrass. Shutters. Uplongs | C170 |
| | | Curling | Pins for elevator | C170 |
| 20.11.93 | Yorkletts farm | H. R. Mackay | Horse gear. Repair chaff cutter | C170 |
| 2.11.93 | Newchurch mill | | Tail bearing. Sweep repairs | C171 |
| 14.11.93§ | | Horsnaill | Chaff cutter | C172 |
| 27.11.93 | Westbere | E. Palmer | Advance Grater | C173 |
| | Whitstable mill | Feakins | Stone nuts sizes | C173 |
| 28.11.93 | | Peters & Davis | Pulley bushes for log frame | C173 |
| 13.12.93 | Eastry mill | W. Clark | Sweep repairs | C174 |
| 18.12.93 | | F. Clarke | Mortice wheel | C174 |

| | | | | |
|----------|----------------------------|--------------|---|--------------|
| | Preston mill | Dunn | Sweep repairs. Shutters diagram sizes | C175/176 |
| | Sandwich mill | Harvey | Worm and bearings for Corcoran. Pulley for grind mill | C177 |
| 2.1.94 | Field mill Charing Heath | Hicks | Pulleys. Belt | C179 |
| 18.1. 94 | New House | Miles | Seed drill repair | C179 |
| 5.2.94 | Bridge | | Roll. Gange fittings. Wheel scrapers | C180 |
| | Sheldwich | F. L. Cobb | Tube brushes | C180 |
| | Sarre | Steddy | New cogs | C180 |
| | Kearsney Phipps Paper mill | Crawshaw | Names addresses manager and owners | C181 |
| | Chartham paper mill | | Cogs turbine shaft, spur wheel sizes | C181/182 |
| 6.3.94 | Deal mill | English | Midling. Sweeps sizes diagrams | C183/184/185 |
| | Lenhall | Matthew Bell | Peak runner 2' 9" dia. Brasses | C186 |
| | Blean mill | | Sweep. Fan flier Sizes. Diagrams | C187/188 |
| | Hoath mill | Taylor | Cogs for stone nuts | C189 |
| | Local Board | | Stand pipe for cattle market | C189 |
| | Guston | Mummery | Midling sizes. Wrot shaft diagram | C190 |
| 17.3.94 | Uphill Mill | Kettle | Cheek pieces. Standards. Cross. Striking rod irons diags. Sizes | C192 |
| | Chartham | E. Colthup | Shim points | C193 |
| 21.3.94 | Elham mill | Sutton | Sweep repairs | C193 |

| | | | | |
|---------|------------------------|--------------|--|----------|
| 20.3.94 | Herne mill | Wooton | Midling repairs sizes | C194 |
| 21.3.94 | Herne | S. Swinford | Tubes for engine | C194 |
| 21.3.94 | Egerton mill | Millgate | Richmonds B&R mill. Boards. Screws. Sack hooks | C195 |
| | Chartham | Colthup | Rollers. Pins | C196 |
| | Manstone | Perkins | Lagging for engine boiler | C196 |
| | Drapers mill | Ind | Peak runner | C196 |
| | Naccott | Amos | Fasteners for driving band to brick machine | C197 |
| 9.4.94 | Wingham mill | Maplesden | Midling sizes | C197 |
| 10.4.94 | Egerton mill | Millgate | Jumper wire | C198 |
| | Wye watermill | Kennett | Covering for silk. Starts for waterwheel | C198 |
| 12.4.94 | Eastry mill | Clark | New shafting, gears, pulleys. Diagram. Sizes | C199/200 |
| | Littlebourne watermill | Jarvis | New wheel sizes | C201 |
| 18.4.94 | Harbledown mill | Hancock | Sweep bar sizes | C202 |
| 18.4.94 | Preston mill | Mrs Solley | Peak runner. Cogs for brake wheel Curb hoop | C202 |
| | Quex farm | | Pump shaft end diagram | C202 |
| 19.4.94 | St Dunstans | Flint & Sons | Rods for pumps | C203 |
| 25.4.94 | Chislett mill | Wooton | Sack roll size. Report brake wheel cogs thin | C203 |
| 26.4.94 | Sarre mill | G. Steddy | Repairs to engine. Gears on spur nut | C204 |
| | Egerton Field mill | Hicks | Pulleys | C205 |
| | Wye mill | Kennett | Cogs for spur wheel sizes | C205 |
| 25.5.94 | Naccott | Young | Front axle for truck diagram sizes | C206 |
| 11.7.94 | Chislett | Wooton | Repair Progress reaper | C209 |

| | | | | |
|---------|-------------------------------|--------------------|--|----------|
| 17.7.94 | New Romney mill | | Curb cogs, repair sweep | C210 |
| | Littlebourne mill | Jarvis | Oak | C211 |
| 24.7.94 | East Kent Hotel Whitstable | Pout | Parts Progress reaper | C211 |
| | | Woollett | Bale of twine | C211 |
| 26.7.94 | | Steed | 1 1/2cwt twine | C211 |
| 15.8.94 | | Monins | Smoke box | C212 |
| | Ebbsfleet | Pearce | Water tanks for cattle | C212 |
| | Sandwich | Larkin | Bearings | C212 |
| 4.9.94 | | Williamson | Hangers. Blocks | C213 |
| | Herne mill | Wootton | Step brass upright shaft. Shutter repairs | C214 |
| | Brook mill | Hancock | Wire for cylinder | C215 |
| 11.9.94 | Ashford | Brown | Gland for slide spindle | C215 |
| | | Peters & Davis | Bush for band saw pulley. Engine chimney. Shafting | C215/216 |
| 12.9.94 | Upper Deal mill | Matson | Sheets and brushes for cylinder | C217 |
| 12.9.94 | Northbourne mill | Fuller | Chimney for engine sizes | C217 |
| 17.9.94 | | Ashenden (Butcher) | Grindstone | C217 |
| | Sevenoaks | Harris | Step brass size | C218 |
| | Kennington mill | Stanley | Steam side tackle diagrams | C219/220 |
| | Kennington mill | Stanley | Water Side elevators diagrams | C221/222 |
| 18.2.95 | Beverley farm | Maxted | Knife and pinion for chaff cutter | C223 |

| | | | | |
|----------|-------------------------|--------------|--|----------|
| 11.6.95 | Cladish | | Price for cultivating 8/6 per acrs. 14/- for twice | C223 |
| | Coleshill mill | | Measure of sweeps. Stone nut gearing | C223/224 |
| 12.11.95 | Ashford | Brown | Bush for pulley | C224 |
| | Aldington mill | Bills | Cheek pieces | C224 |
| | Queen Street brewery | | Work to get ready for engine | C225 |
| | | Flint & Sons | Get ready gear for mash tun | C226 |