

EKMG no.	Location	Medium	Mill	Date	Notes	Catalogue no.
060101	Aldeburgh	Photograph		1949	Sign of The Mill Inn, Aldeburgh	
060201	Barnham	Photograph	Tower mill, Barnham	1961	Derelict, Cap missing, two sweeps remain	
060301	Barnham	Photograph	Tower mill, Barnham	1963	Derelict, Cap missing, two sweeps remain	
060401	Bardwell	Photograph	Tower mill, Bardwell	1961	Derelict	
060501	Blundeston	Photograph	Tower mill, Blundeston	1962	Derelict, cap missing	
060601	Buxhall	Photograph	Tower mill, Buxhall	1961	Derelict, cap missing	
060701	Blo Norton	Photograph	Tower mill, Blo Norton	1960	Derelict	
060801	Blo Norton	Photograph	Tower mill, Blo Norton	1960	Derelict	
060901	Bramfield	Photograph	Waterloo Mill	1949	Derelict, cap missing	
061001	Burgh	Photograph	Tower mill, Burgh	1959	Derelict, cap missing	
061101	Clare	Photograph	Chilton Street Mill	1961	Derelict, cap missing	
061201	Cockfield	Photograph	Tower mill, Cockfield	1959	Derelict, cap missing	
061301	Crowfield	Photograph	Smock mill, Crowfield	1960	Derelict, cap missing	
061401	Debenham	Photograph	Tower mill, Debenham	1949	Derelict, two sweeps remaining	
061501	Debenham	Photograph	Tower mill, Debenham	1949	Derelict, two sweeps remaining	
061601	Debenham	Photograph	Tower mill, Debenham	1958	Derelict, two sweeps remaining	
061701	Debenham	Photograph	Tower mill, Debenham	1960	Derelict, two sweeps remaining	
061801	Debenham	Photograph	Tower mill, Debenham	1960	Derelict, two sweeps remaining	
061901	Debenham	Photograph	Tower mill, Debenham	1960	Interior: brake wheel and wallower	
062001	Debenham	Photograph	Tower mill, Debenham	1960	Interior: wheels for turning cap	
062101	Debenham	Photograph	Tower mill, Debenham	1960	Interior: vat and hopper	
062201	Debenham	Photograph	Tower mill, Debenham	1960	Interior: millstones, caliper and swinging arm	
062301	Debenham	Photograph	Tower mill, Debenham	1960	Interior: spur wheel and stone nuts	
062401	Debenham	Photograph	Tower mill, Debenham	1960	Interior: flour bin	
062501	Debenham	Photograph	Tower mill, Debenham	1960	Interior: light fixture	
062601	Debenham	Photograph	Tower mill, Debenham	1961	Derelict, two sweeps remaining	
062701	Debenham	Photograph	Tower mill, Debenham	1961	Derelict, two sweeps remaining	
062801	Debenham	Photograph	Tower mill, Debenham	1962	Derelict, two sweeps remaining	
062901	Dalham	Photograph	Lower Mill, Dalham	1956	Disused, fantail missing	
063001	Dalham	Photograph	Lower Mill, Dalham	1961	Disused, fantail missing	
063101	Dalham	Photograph	Lower Mill, Dalham	1961	Disused, fantail missing	
063201	Drinkstone	Photograph	Post mill, Drinkstone	1956	Derelict	

063301	Drinkstone	Photograph	Smock mill, Drinkstone	1956	Derelict, sweeps missing
063401	Drinkstone	Photograph	Post mill, Drinkstone	1959	Disused
063501	Drinkstone	Photograph	Smock mill, Drinkstone	1959	Derelict, sweeps missing
063601	Drinkstone	Photograph	Post mill, Drinkstone	1960	Disused
063701	Drinkstone	Photograph	Post mill, Drinkstone	1960	Disused
063801	Drinkstone	Photograph	Post mill, Drinkstone	1960	Fan carriage
063901	Drinkstone	Photograph	Post mill, Drinkstone	1960	Interior: chute and vat
064001	Drinkstone	Photograph	Post mill, Drinkstone	1960	Interior: govenor
064101	Drinkstone	Photograph	Post mill, Drinkstone	1960	Interior: trestle
064201	Drinkstone	Photograph	Post mill, Drinkstone	1961	In working order
064301	Drinkstone	Photograph	Post mill, Drinkstone	1962	In working order
064401	Earl Soham St. James South	Photograph	Kent's Mill	1949	Round house only, house conversion
064501	Elmham	Photograph	Post mill, St. James South Elmham	1962	Round house only, rooved
064502	Hopton	Photograph	Tower mill, Hopton	1962	House conversion, cap replaced
064503	Thorndon	Photograph	Post mill, Thorndon	1962	Round house only, rooved
064601	Eye	Photograph	Mortimer's Mill	1960	Collapsed
064701	Eye	Photograph	Mortimer's Mill	1960	Trestle with carving
064801	Eye	Photograph	Mortimer's Mill	1960	Windshaft and gears in undergrowth
064901	Eye	Photograph	Mortimer's Mill	1959	Gears in undergrowth
065001	Framsden	Photograph	Webster's Mill	1949	Disused
065101	Framsden	Photograph	Webster's Mill	1949	Disused
065201	Framsden	Photograph	Webster's Mill	1949	Fan carriage
065301	Framsden	Photograph	Webster's Mill	1958	Disused
065401	Framsden	Photograph	Webster's Mill	1959	Good condition
065501	Framsden	Photograph	Webster's Mill	1960	Good condition
065601	Framsden	Photograph	Webster's Mill	1960	Good condition
065701	Framsden	Photograph	Webster's Mill	1962	Good condition
065801	Fressingfield	Photograph	Fisher's Mill	1959	Round house only, re-rooved
065901	Freckenham	Photograph	North Mill	1963	Derelict, cap missing
066001	Friston	Photograph	Post mill, Friston	1949	Good condition, two sweeps remaining
066101	Friston	Photograph	Post mill, Friston	1949	Fan carriage
066201	Friston	Photograph	Post mill, Friston	1949	Bottom of fan carriage

066301	Friston Garboldisham	Photograph	Post mill, Friston	1962	Bottom of fan carriage
066401	Common Garboldisham	Photograph	Post mill, Garboldisham Common	1960	Derelict
066501	Common	Photograph	Post mill, Garboldisham Common	1960	Derelict
066601	Great Welnetham	Photograph	Tutelina Mills	1959	Disused, cap replaced
066701	Halesworth	Photograph	Calver's Mill	1937	In working order
066801	Halesworth	Photograph	Calver's Mill	1937	In working order
066901	Halesworth	Photograph	Calver's Mill	1949	Derelict, sweeps missing
067001	Holton St. Peter	Photograph	Post mill, Holton St. Peter	1949	Derelict
067101	Holton St. Peter	Photograph	Post mill, Holton St. Peter	1949	Derelict
067201	Holton St. Peter	Photograph	Post mill, Holton St. Peter	1949	Bottom of fan carriage
067301	Holton St. Peter	Photograph	Post mill, Holton St. Peter	1949	Fan carriage
067401	Holton St. Peter Garboldisham	Photograph	Post mill, Holton St. Peter	1962	Derelict
067501	Common Garboldisham	Photograph	Post mill, Garboldisham Common	1962	Derelict
067601	Common Ilketshall St.	Photograph	Post mill, Garboldisham Common	1962	Trestle
067701	Lawrence	Photograph	Tower mill, Ilketshall St. Lawrence	1949	Disused, cap replaced
067801	Kelsale cum Carlton	Photograph	Skoulding's Mill	1949	derelict, fan tail and sweeps missing
067901	Occold	Photograph	Smock mill, Occold	1960	Brick base only remaining, re-rooved