

FWG-02510	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
FOREIGN01_01.JPG	Russia/Poland	Group of three preserved post mills with sails	late C20	On at least two of the mills, the superstructure appears to be carried down to cover the substructure
FOREIGN01_02.JPG	Russia/Poland	Preserved open-trestle post mill with sails; preserved mill of indeterminate type, with sails, in background	late C20	
FOREIGN01_03.JPG	Russia/Poland	The two mills shown in the previous photograph; preserved shingled post or possibly smock mill in foreground, the preserved open-trestle post mill in background	late C20	
FOREIGN01_04.JPG	Russia/Poland	Preserved post mill with sails; site probably open-air museum (sail of another mill visible above trees in mid-distance)	late C20	
FOREIGN01_05.JPG	Russia/Poland	Preserved smock mill with ogee cap, common sails and tailpole	late C20	
FOREIGN01_06.JPG	Russia/Poland?	Derelect smock or tower mill with cap, one stock and part of fantail	late C20	
HOLLAND01_01.JPG	Holland	winding wheel and tailpole on stage of preserved smock (probably) mill; preserved paltrok mill in background	May-73	Negative only
HOLLAND01_02.JPG	Holland - museum	Part of preserved wood/brick watermill building showing undershot waterwheel	May-73	
HOLLAND01_03.JPG	Holland - museum	Part of preserved watermill building with wheel; preserved hollow-post mill in background, sails turning	May-73	
HOLLAND01_04.JPG	Holland	preserved hollow-post mill (sails turning)	May-73	
HOLLAND01_05.JPG	Holland	Two men working on sail of preserved hollow-post mill, with one of them climbing sail	May-73	
HOLLAND01_06.JPG	Holland	Poor view of man working on sail of preserved hollow-post mill	May-73	
HOLLAND01_07.JPG	Holland	Preserved "polder" mill (hollow-post mill) with sails turning	May-73	
HOLLAND01_08.JPG	Holland	Interior view of polder mill showing hollow post	May-73	
HOLLAND01_09.JPG	Holland - Kinderdijk	View of mills working	May-73	
HOLLAND01_10.JPG	Holland - Kinderdijk	View of mills working	May-73	
HOLLAND01_11.JPG	Holland - Kinderdijk	View of mills working	May-73	
HOLLAND01_12.JPG	Holland - Kinderdijk	View of mills working	May-73	
HOLLAND01_13.JPG	Holland - Kinderdijk	View of mills working	May-73	
HOLLAND01_14.JPG	Holland - double watermill	Exterior view of preserved watermill building with two wheels	May-73	
HOLLAND01_15.JPG	Holland	Preserved wood/brick watermill building with undershot wheel	May-73	
HOLLAND01_16.JPG	Holland - windmill	As 01-01	May-73	
HOLLAND01_17.JPG	Holland	view of drainage mills on polder seen through winding wheel of preserved mill	May-73	

HOLLAND01_18.JPG	Holland - probably Amsterdam, De Gooijer	Tall derelict smock mill without sails	May-73	
HOLLAND01_19.JPG	Holland - watermill	Exterior view of preserved watermill building with wheel	May-73	
HOLLAND01_20.JPG	Holland - watermill	Launder and wheel of watermill - picture very dark	May-73	
HOLLAND02_01.JPG	Holland - windmill	Tall preserved smock mill with Dekkerised sails	May-73	
HOLLAND02_02.JPG	Holland - windmill	Closeup of longitudinal shutters on same mill as above	May-73	
HOLLAND02_03.JPG	Holland - windmill	Tall thatched mill with dekkerised sails	May-73	Same mill as in 02_01-2
HOLLAND02_04.JPG	Holland - Schermer Museum	Pair of preserved smock drainage mills	May-73	
HOLLAND02_05.JPG	Holland - Schermer Museum	Wooden Archimedean screw with sail and part of body of preserved smock drainage mill in background	May-73	
HOLLAND02_06.JPG	Holland - Schermer Museum	Mid-distant view of preserved smock mill	May-73	
HOLLAND02_07.JPG	Holland - Herbouw, Mill De Kat	Framing of new smock mill under construction	May-73	
HOLLAND03_01.JPG	Holland	Interior of watermill(?) showing gearing	May-73	
HOLLAND03_02.JPG	Holland	Preserved smock mill on mound	May-73	
HOLLAND03_03.JPG	Holland	Horse mill with edge runner stones in barn	late C20	
HOLLAND03_04.JPG	Holland	Horse mill with edge runner stones in barn	late C20	
HOLLAND03_05.JPG	Holland - horse mill	Horse and horse gin in barn	late C20	
HOLLAND03_06.JPG	Holland	Preserved watermill building with wheel	late C20	
HOLLAND03_07.JPG	Holland	Preserved watermill building with wheel	late C20	Same mill as previous view
HOLLAND03_08.JPG	Holland	View of wheel of unidentified watermill	late C20	
HOLLAND03_09.JPG	Holland	Preserved double watermill at work	late C20	
HOLLAND03_10.JPG	Holland	Part of exterior of preserved watermill building at work	late C20	
HOLLAND03_11.JPG	Holland	View of double wheel of preserved watermill	late C20	
JILL01_01.JPG	Sussex: Clayton, "Jill"	fan carriage on ground	1984	Michael Peat & Danny Jarmann
JILL01_02.JPG	Sussex: Clayton, "Jill"	fan carriage being raised	1984	
JILL01_03.JPG	Sussex: Clayton, "Jill"	fantail carriage from above	late C20	
JILL01_04.JPG	Sussex: Clayton, "Jill"	view with Jack in b/g	late C20	
JILL01_05.JPG	Sussex: Clayton, "Jill"	peak runner being dressed	Sep-83	Sid Ashdown
JILL01_06.JPG	Sussex: Clayton, "Jill"	view with Jack in b/g	late C20	
JILL01_07.JPG	Sussex: Clayton, "Jill"	peak runner being dressed	Sep-83	Sid Ashdown
JILL01_08.JPG	Sussex: Clayton, "Jill"	profiling the face of the brakewheel	late C20	using lathe tool to true the face of the brakewheel
JILL01_09.JPG	Sussex: Clayton, "Jill"	peak stones dressed	late C20	
JILL01_10.JPG	Sussex: Clayton, "Jill"	re-cogging brakewheel	1984/5	Michael Peat

JILL01_11.JPG	Sussex: Clayton, "Jill"	int - governor & sack	1984/5	
JILL01_12.JPG	Sussex: Clayton, "Jill"	view of Jill from the cap of Jack	late C20	
JILL01_13.JPG	Sussex: Clayton, "Jill"	view with people & bag of flour - event to celebrate Jill's return to working order	Jul-86	left to right : husband of mayoress, mayoress, Danny Jarmann, Claudine Longhurst, Michael Hoddell
JILL01_14.JPG	Sussex: Clayton, "Jill"	Dressed overall with visitors	Jul-86	
JILL01_15.JPG	Sussex: Clayton, "Jill"	Lady with white hat in roundhouse	Jul-86	Claudine Longhurst unveiling Dorothea plaque
JILL01_16.JPG	Sussex: Clayton, "Jill"	Lady with white hat in roundhouse	Jul-86	Claudine Longhurst
JILL01_17.JPG	Sussex: Clayton, "Jill"	wide shot of mill dressed overall	Jul-86	
JILL01_18.JPG	Sussex: Clayton, "Jill"	Millstones outside mill	late C20	Two peak stones and one cullen stone
JILL01_19.JPG	Sussex: Clayton, "Jill"	Rear view with broken fan	1987	Oct 1987 storm damage
JILL01_20.JPG	Sussex: Clayton, "Jill"	Looking up at weatherboard damage	late C20	Oct 1987 storm damage
JILL02_01.JPG	Sussex: Clayton, "Jill"	Top of post	late C20	
JILL02_02.JPG	Sussex: Clayton, "Jill"	Quant & brake lever	late C20	
JILL02_03.JPG	Sussex: Clayton, "Jill"	Rot on corner post	late C20	
JILL02_04.JPG	Sussex: Clayton, "Jill"	Wire machine	late C20	
JILL02_05.JPG	Sussex: Clayton, "Jill"	Lightning damage on stock	1983	
JILL02_06.JPG	Sussex: Clayton, "Jill"	Fantail boss with Jill in b/g	late C20	
JILL02_07.JPG	Sussex: Clayton, "Jill"	Trestle and collar	late C20	
JILL02_08.JPG	Sussex: Clayton, "Jill"	Tailwheel from below	late C20	
JILL02_09.JPG	Sussex: Clayton, "Jill"	Damage to front corner post	late C20	
JILL02_10.JPG	Sussex: Clayton, "Jill"	Working on sweep frames in snow	1979	Frank Gregory & Martin Brunnarius
JILL02_11.JPG	Sussex: Clayton, "Jill"	Removing sweep bolt	1979	Frank Gregory on sweep
JILL02_12.JPG	Sussex: Clayton, "Jill"	Preparing to lower sweep	1979	Frank Gregory on sweep
JILL02_13.JPG	Sussex: Clayton, "Jill"	Sweep being lowered	1979	
JILL02_14.JPG	Sussex: Clayton, "Jill"	Rear view with scaffolding	1979/80	
JILL02_15.JPG	Sussex: Clayton, "Jill"	Lifting timber through rear door	late C20	new breastbeam being taken into mill
JILL03_01.JPG	Sussex: Clayton, "Jill"	Working on sails on ground	late C20	Martin Brunnarius on right
JILL03_02.JPG	Sussex: Clayton, "Jill"	Shepherds in smocks with stall	late C20	Frank Gregory on clayton green
JILL03_03.JPG	Sussex: Clayton, "Jill"	Sail stock in barn being worked on	late C20	
JILL03_04.JPG	Sussex: Clayton, "Jill"	Rear view with full sails	late C20	
JILL03_05.JPG	Sussex: Clayton, "Jill"	Stock being raised/lowered	late C20	

JILL03_06.JPG	Sussex: Clayton, "Jill"	Int repairs to framing at corner	late C20	
JILL03_07.JPG	Sussex: Clayton, "Jill"	Sweeps and fan frame being assembled on ground	1985	
JILL03_08.JPG	Sussex: Clayton, "Jill"	Fantail from above	late C20	
JILL03_10.JPG	Sussex: Clayton, "Jill"	Sail stock in barn being worked on	late C20	
JILL03_11.JPG	Sussex: Clayton, "Jill"	Mill with full sweeps from rear	late C20	
JILL03_12.JPG	Sussex: Clayton, "Jill"	Int - front pair of millstones & stone furniture complete	late C20	
JILL03_13.JPG	Sussex: Clayton, "Jill"	Crane preparing fan carriage lift	Mar-84	
JILL03_14.JPG	Sussex: Clayton, "Jill"	Stock being lifted in	late C20	
JILL03_15.JPG	Sussex: Clayton, "Jill"	Full sweeps Jack in b/g	late C20	
JILL03_16.JPG	Sussex: Clayton, "Jill"	With 3 sweep frames	late C20	
JILL03_17.JPG	Sussex: Clayton, "Jack"	Heap of remains of Jack's sweep	1983	Duncton roundhouse in background
JILL03_18.JPG	Sussex: Clayton, "Jill"	Partially shuttered sweeps Jack in b/g	late C20	
JILL03_19.JPG	Sussex: Clayton, "Jill"	Stocks only scaffolded in snow	late C20	
JILL03_20.JPG	Sussex: Clayton, "Jill"	Stock being raised/lowered	late C20	
JILL04_01.JPG	Sussex: Clayton, "Jill"	Sweep frame being lowered	late C20	
JILL04_02.JPG	Sussex: Clayton, "Jill"	Sweep frames only with tail scaffolded. Jack in b/g	late C20	
JILL04_03.JPG	Sussex: Clayton, "Jill"	Sweep frames only	late C20	Duncton roundhouse in background
JILL04_04.JPG	Sussex: Clayton, "Jill"	Fitting lower sweep frame	late C20	
JILL04_05.JPG	Sussex: Clayton, "Jill"	raising/lowering sweep frame	late C20	
JILL04_06.JPG	Sussex: Clayton, "Jill"	Second stock being lowered	late C20	
JILL04_07.JPG	Sussex: Clayton, "Jill"	Crane lifting fan carriage	Mar-84	
JILL04_08.JPG	Sussex: Clayton, "Jill"	Fan carriage having been lifted into place	Mar-84	
JILL04_09.JPG	Sussex: Clayton, "Jill"	Pair of sweeps ready on ground	Jul-86	
JILL04_10.JPG	Sussex: Clayton, "Jill"	Party of VIPs with bag of flour	late C20	left to right : husband of mayoress, mayoress, Tim Renton, Claudine Longhurst, Michael Hoddell
JILL04_11.JPG	Sussex: Clayton, "Jill"	With sweep frames only Jack in b/g	late C20	
JILL04_12.JPG	Sussex: Clayton, "Jill"	coloured postcard	circa 1905	
JILL04_13.JPG	Sussex: Clayton, "Jill"	With sweep frames only Jack in b/g	late C20	
JILL04_14.JPG	Sussex: Clayton, "Jill"	1847 watercolour of Dyke Road mills	late C20	
JILL04_15.JPG	Sussex: Clayton, "Jill"	Removing bolts of last sweep	late C20	Frank Gregory on sweep
JILL04_16.JPG	Sussex: Clayton, "Jill"	Dressing peak stone - dark	late C20	Sid Ashdown
JILL04_17.JPG	Sussex: Clayton, "Jill"	Mill working on open day	late C20	
JILL04_18.JPG	Sussex: Clayton, "Jill"	using lathe tool to true the face of the brakewheel	late C20	
JILL04_19.JPG	Sussex: Clayton, "Jill"	Dressing peak stones	late C20	Sid Ashdown

JILL04_20.JPG	Sussex: Clayton, "Jill"	Raising fourth sweep frame	late C20	
JILL05_01.JPG	Sussex: Clayton, "Jill"	Lifting new stock with crane	late C20	
JILL05_02.JPG	Sussex: Clayton, "Jill"	Fan carriage rising - MJP looks cold!	Mar-84	
JILL05_03.JPG	Sussex: Clayton, "Jill"	Breast scaffolded - stocks only	late C20	
JILL05_04.JPG	Sussex: Clayton, "Jill"	Working on sweep frames	late C20	
JILL05_05.JPG	Sussex: Clayton, "Jill"	two sweep frames only Jack in b/g	late C20	
JILL05_06.JPG	Sussex: Clayton, "Jill"	Stock in workshop	late C20	
JILL05_07.JPG	Sussex: Clayton, "Jill"	Interior framing	late C20	
JILL05_08.JPG	Sussex: Clayton, "Jill"	Interior framing	late C20	
JILL05_10.JPG	Sussex: Clayton, "Jill"	re-flooring roundhouse	late C20	Martin Brunnarius
JILL05_11.JPG	Sussex: Clayton, "Jill"	stocks only - scaffolded	late C20	
JILL05_12.JPG	Sussex: Clayton, "Jill"	Lifting 4th sweep frame	late C20	
JILL05_13.JPG	Sussex: Clayton, "Jill"	FWG working on sweep frame	late C20	
MACHINI01_01.JPG	Holland	Dust floor of smock mill showing curb and winding gear	late C20	
MACHINI01_02.JPG	Holland	Dust floor of smock mill showing curb and winding gear	late C20	
MACHINI01_03.JPG	Holland	Dust floor of smock mill showing curb and winding gear	late C20	
MACHINI01_04.JPG	Holland	Dust floor of smock mill showing curb and winding gear	late C20	
MACHINI01_05.JPG	Holland	Dust floor of smock mill showing winding gear and brakewheel	late C20	
MACHINI01_06.JPG	Unknown	Gearing from wind- or watermill lying among bushes	late C20	
MACHINI01_07.JPG	Unknown	Gearing from wind- or watermill lying among bushes	late C20	
SUSSEXHANTS01_01	Sussex: Durrington, High Salvington	mill being turned on open day	late C20	
SUSSEXHANTS01_02	Sussex: Durrington, High Salvington	Old postcard showing interior of roundhouse of café	early C20	
SUSSEXHANTS01_03	Unknown	Museum showcase with info board on "The Miller's Tomb"	late C20	Is tomb in question that of John Oliver at Highdown Hill?
SUSSEXHANTS01_04	Unknown	Old coloured plan of some land, probably C16 or C17, with illustration of post mill on it		
SUSSEXHANTS01_05	Sussex: Angmering, Ecclesden Mill	House-converted tower of tower mill	late C20	
SUSSEXHANTS01_06	Sussex: Durrington, High Salvington	Volunteers fitting new weatherboarding to buck roof during restoration	1980s	Peter Casebow, Roger Ashton, Bob Potts, Ron Hurd
SUSSEXHANTS01_07	Sussex: Shipley, King's Mill	Preserved smock mill with sails	c 1992	
SUSSEXHANTS01_08	Sussex: Waldron, Cross-in-Hand, New Mill	Post mill in working order	1960-69	
SUSSEXHANTS01_09	Sussex: Nutley	Restored post mill with cloths set on sails	late C20	
SUSSEXHANTS01_10	Sussex: Broadwater	Post mill in w/o	late C19 or early C20	

SUSSEXHANTS01_11	Sussex: Worthing, Navarino Mills	Tower and smock mill, former in w/o, latter without fan	late C19 or early C20	
SUSSEXHANTS01_12	Sussex: Worthing, Heene Mill	Disused post mill with four sails	late C19 or early C20	
SUSSEXHANTS01_13	Sussex: Worthing, Sea Mill post mill	Derelict post mill with sails and remains of fantail	late C19 or early C20	This formerly stood at Cross Street, Worthing
SUSSEXHANTS01_14	Hants: Chalton	Derelict tower mill with windshaft, part of one stock and remains of fanstage	prob. 1960s	
SUSSEXHANTS01_15	Hants: Chalton	House-converted tower mill with dummy cap and sails	post-1978	
SUSSEXHANTS01_16	Hants: Portsmouth, Dock Mill	Artificially coloured postcard showing disused (as windmill) tower mill with four sails	late C19 or early C20	
SUSSEXHANTS01_17	Hants: Bursledon	Restored tower mill with cloths set on sails	late 1980s or 1990s	
SUSSEXHANTS01_18	Prob. Eastern Europe	Group of post mills with sails, all apparently preserved: substructures are hidden by the bodies of the mills	late C20	
VARIOUS01_01.JPG	Sussex: Nutley	Restored post mill with sails	late C20	
VARIOUS01_02.JPG	Unknown	Watermill building scaffolded for restoration/conversion	late C20	
VARIOUS01_03.JPG	Buckinghamshire: Lacey Green	Tower of smock mill scaffolded for repair, with old cap on ground	c1971	
VARIOUS01_04.JPG	Northamptonshire: Hellidon	Derelict tower mill with brakewheel and remains of cap and three sails (two visible)	early to mid-1970s	
VARIOUS01_05.JPG	Warwickshire: Napton-on-the-Hill	Preserved tower mill with cap and sails	mid-1970s	
VARIOUS01_06.JPG	Warwickshire: Napton-on-the-Hill	Preserved tower mill with cap and sails	mid-1970s	
VARIOUS02_01.JPG	Foreign	Interior of post mill showing brakewheel, stone nut and one pair of stones	late C20	
VARIOUS02_02.JPG	Foreign	Interior of smock mill showing hurst frame, upright shaft, great spur wheel and lantern pinion stone nut	late C20	
VARIOUS02_03.JPG	Foreign?	Interior of smock mill showing upright shaft, crown wheel and one pair of stones	late C20	
VARIOUS02_04.JPG	Foreign?	Interior of smock mill showing bevel gear	late C20	
VARIOUS02_05.JPG	Unknown	Main post (of post mill) and driving shaft of windmill inside unidentified building beside Greek-style colonnade	late C20	
VARIOUS02_06.JPG	Sussex: Keymer, Oldland Mill	Derelict sailless post mill supported by props pending restoration	c1990	
VARIOUS02_07.JPG	Unknown	Workshop in which part of frame of new post mill buck is being made up - prob. for Oldland Mill, Keymer, Sussex	c1990	Ask Philip Hicks for ID

VARIOUS02_08.JPG	Sussex: Durrington, High Salvington	Overexposed view of part of buck and sails of restored post mill	1990s or late 1980s	
VARIOUS02_09.JPG	Sussex: Durrington, High Salvington	Mill as preserved with common sails and concrete roundhouse	mid-late C20	
VARIOUS02_10.JPG	Sussex: Durrington, High Salvington	Mill as preserved with common sails and concrete roundhouse	mid-late C20	
VARIOUS02_11.JPG	Sussex	New fantail for Polegate mill being built in workshop	late C20	
VARIOUS02_12.JPG	Sussex	New fantail for Polegate mill being built in workshop	late C20	
VARIOUS02_13.JPG	Sussex	New fantail for Polegate mill being built in workshop	late C20	
VARIOUS03_01.JPG	Cambs: Impington	Preserved smock mill with cap, fan and stocks	late C20	
VARIOUS03_02.JPG	Unknown	Surviving post mill trestle with windshaft nearby	late C20	
VARIOUS03_03.JPG	Unknown	Surviving post mill trestle with windshaft nearby	late C20	
VARIOUS03_04.JPG	Unknown	Preserved watermill building with wheel	late C20	
VARIOUS03_05.JPG	Terwick watermill Trotton West Sussex	Preserved watermill building before conversion	late C20	
VARIOUS03_06.JPG	Kent: Cranbrook, Union Mill	preserved smock mill floodlit	late C20	
VARIOUS03_07.JPG	Kent: Cranbrook, Union Mill	preserved smock mill floodlit	late C20	
VARIOUS03_08.JPG	Lincs: Legbourne	Preserved tower of combined wind- and watermill with waterwheel and dummy cap (image partly obscured)	late C20	
VARIOUS03_09.JPG	Lincs: Legbourne	Preserved tower of combined wind- and watermill with waterwheel and dummy cap	late C20	
VARIOUS03_10.JPG	Unknown	Tombstone with post mill carving	late C20	Ask SPAB for ID
VARIOUS03_11.JPG	Sussex: Barnham	Picture of open-trestle post mill with common sails, from inn sign (overexposed)	late C20	
VARIOUS03_12.JPG	Sussex: Barnham	Picture of open trestle postmill with common sails, from inn sign	photo taken late C20	
VARIOUS03_13.JPG	Sussex: Barnham	Interior of tower mill showing windshaft, b/w and cap roof framing	late C20	
VARIOUS03_14.JPG	Sussex: Barnham	Interior of tower mill showing great spur wheel with auxiliary gear ring, and stone nut	late C20	
VARIOUS03_15.JPG	Sussex: Polegate	Interior of tower mill showing great spur wheel with auxiliary gear ring	late C20	
VARIOUS03_17.JPG	Sussex: Polegate	Great spur wheel with auxiliary gear ring, and stone nut	late C20	
	Sussex: Polegate	Part of great spur wheel	late C20	
VARIOUS03_18.JPG	Sussex: Polegate	View of stone floor showing two pairs of stones	late C20	
VARIOUS03_19.JPG	Unknown	Exterior of watermill building showing double waterwheel	late C20	
VARIOUS03_20.JPG	Unknown	Museum display including what appears to be winding worm of windmill	late C20	

VARIOUS04_01.JPG	Sussex: Groombridge	Postcard showing part of exterior of watermill building with wheel	late C19 or early C20	
VARIOUS04_02.JPG	Unknown	Exterior of watermill building showing remains of double wheel	late C20	
VARIOUS04_03.JPG	Sussex: Sheffield Mill	Watermill building in course of repair, with wheel	late C20	
VARIOUS04_04.JPG	Unknown	Interior of post mill showing brakewheel, stones and unidentified iron gearwheel	late C20	
VARIOUS04_05.JPG	Unknown	Pew kneeler with embroidered design of Argos Hill post mill, Mayfield, Sussex	late C20	
VARIOUS04_06.JPG	Channel Islands: Sark	Preserved tower of tower mill with replica(?) ogee cap	late C20	
VARIOUS04_07.JPG	Unknown	Interior of tower mill showing cap frame, curb and truck wheel	late C20	
VARIOUS04_08.JPG	Kent: Wittersham, Stocks Mill	Preserved post mill with one sail missing (photo taken before removal of gallery at side of mill)	mid-late C20	
VARIOUS04_09.JPG	Kent: Wittersham, Stocks Mill	Preserved post mill with one sail missing (photo taken before removal of gallery at side of mill)	mid-late C20	
VARIOUS04_10.JPG	Kent, Wittersham, Stocks Mill	Double exposure: tailwheel superimposed over image of interior of unidentified building	late C20	
VARIOUS04_11.JPG	Kent, Wittersham, Stocks Mill	Clasp arm brakewheel	late C20	
VARIOUS04_12.JPG	Sussex: Winchelsea, St Leonards' Mill	Preserved post mill without sails	late C20 (before gale damage of 1977-8)	
VARIOUS04_13.JPG	Sussex: Shipley, King's Mill	Preserved smock mill with sails	late C20	
VARIOUS04_14.JPG	Sussex: Shipley, King's Mill	Preserved smock mill with sails	late C20	
VARIOUS04_15.JPG	Sussex: Shipley, King's Mill	Preserved smock mill with sails	late C20	
VARIOUS04_16.JPG	Cambs: Bourn	Preserved post mill with sails, taken before replacement of wide weatherboarding	1970s	
VARIOUS04_17.JPG	Prob. foreign	Small stone watermill building	late C20	
VARIOUS04_18.JPG	Prob USA	Unidentified wooden building, possibly watermill; site may be open-air museum or Amish community (for e.g.) as man in foreground wears old-fashioned clothing	late C20	
VARIOUS04_19.JPG	Sussex: Polegate	mill museum with postmill model	late C20	
VARIOUS04_20.JPG	Sussex: Polegate	mill museum with postmill model	late C20	Model was by FWG
VARIOUS05_01.JPG	Sussex: Nutley	Restored post mill with sails	late C20	Model was by FWG
VARIOUS05_02.JPG	Sussex: Nutley	Restored post mill with sails	late C20	
VARIOUS05_03.JPG	Sussex: Nutley	Restored post mill with sails	late C20	
VARIOUS05_04.JPG	Sussex: Nutley	Restored post mill with sails	late C20	

VARIOUS05_05.JPG	Sussex: Nutley	Restored post mill with sails	late C20	
VARIOUS05_06.JPG	Sussex: Nutley	Restored post mill with sails	late C20	
VARIOUS05_07.JPG	Sussex: Nutley	Restored post mill with sails	late C20	
VARIOUS05_08.JPG	Sussex: West Chiltington	House-converted smock mill with two sails	late C20	
VARIOUS05_09.JPG	Unknown	Interior of roundhouse of post mill showing trestle	late C20	
VARIOUS05_10.JPG	Sussex: Arundel, South Marsh Mill	House-converted tower mill with dummy cap	late C20	
VARIOUS05_11.JPG	Sussex: Arundel, South Marsh Mill	View inside cap of house-converted tower mill showing windshaft, breast beam and remains of brakewheel	late C20	Rare view
VARIOUS05_12.JPG	Sussex: Waldron, Cross-in-Hand, New Mill	Derelict fan carriage with broken fan	late C20	contrast with SUSSEXHANTS01_08
VARIOUS05_13.JPG	Eastbourne?	Excavation of round walls in chalk	late C20	Ask Lawrence Stevens for ID
VARIOUS05_14.JPG	Eastbourne?	Excavation of round walls in chalk	late C20	Ask Lawrence Stevens for ID
VARIOUS05_15.JPG	Kent: Eastry, Upper Mill	Repairs under way to cap of sailless smock mill	mid-1970s	
VARIOUS05_16.JPG	Kent: Eastry, Upper Mill	Repairs under way to cap of sailless smock mill	mid-1970s	
VARIOUS05_17.JPG	Unknown	Preserved timber watermill building by pond	late C20	
VARIOUS05_18.JPG	Unknown	Exterior of derelict watermill building by pond, with modern housing in background	late C20	This image has appeared elsewhere in the collection
VARIOUS05_19.JPG	Cheshire: Stretton	Exterior of preserved watermill building	late C20	
VARIOUS05_20.JPG	Cheshire: Stretton	Exterior of preserved watermill building (overexposed)	late C20	
VARIOUS06_01.JPG	Sussex: Icklesham, Hog Hill	Preserved post mill with sail frames and roof fan	late C20	
VARIOUS06_03.JPG	Sussex: Polegate	Wallower and sack hoist	late C20	
VARIOUS06_04.JPG	Sussex: Polegate	Upright shaft	late C20	
	Sussex: Polegate	View of stone floor showing two pairs of stones	late C20	
VARIOUS06_05.JPG	Sussex: Polegate	Smutter and dresser	late C20	
VARIOUS06_06.JPG	Unknown	Detail of roof framing of unidentified building, possibly watermill	late C20	
VARIOUS06_07.JPG	Unknown	Derelict watermill building with chimney	late C20	
VARIOUS06_08.JPG	Unknown	Detail of roof framing of unidentified building, possibly watermill	late C20	Same mill as previous view but one
VARIOUS06_09.JPG	Unknown	Interior of unidentified building showing rotted timberwork	late C20	
VARIOUS06_10.JPG	Unknown	Derelict watermill building with chimney	late C20	Same mill as 06_07
VARIOUS06_11.JPG	Unknown	Four small waterwheels of different type, preserved outside unidentified building	late C20	
VARIOUS06_12.JPG	Sussex: Burton	Sunset over millpond	late C20	
VARIOUS06_13.JPG	Sussex: Cowfold, Eolienne Bolee	Wind engine	late C20	

VARIOUS06_14.JPG	Sussex: Cowfold, Eolienne Bolee	Wind engine	late C20	
VARIOUS06_15.JPG	Unknown	Surviving pylon of wind engine	late C20	
VARIOUS06_16.JPG	Unknown	Shaping a wheel shaft(?) in workshop	late C20	
VARIOUS01_17.JPG	Unknown	Preserved stone watermill building with overshot wheel	late C20	
VARIOUS01_18.JPG	Unknown	Woman with dog inspecting large preserved standalone watermill; overshot, with what appears to be siphon feed	late C20	
VARIOUS01_19.JPG	Unknown	Preserved watermill building by stream	late C20	
VARIOUS01_20.JPG	Unknown	Preserved watermill building by stream	late C20	
VARIOUS07_01.JPG	Sussex: Nutley	Disused post mill with sail frames, before restoration of late 1960s/early 70s	mid-late C20	
VARIOUS07_02.JPG	Sussex: Nutley	Disused post mill with sail frames, before restoration of late 1960s/early 70s	mid-late C20	
VARIOUS07_03.JPG	Sussex: Nutley	Disused post mill with sail frames, before restoration of late 1960s/early 70s	mid-late C20	
VARIOUS07_04.JPG	Sussex: Nutley	Disused post mill with sail frames, before restoration of late 1960s/early 70s	mid-late C20	
VARIOUS07_05.JPG	Surrey: Outwood	Preserved post mill in working order	late C20	
VARIOUS07_06.JPG	Surrey: Outwood	Preserved post mill in working order	late C20	
VARIOUS07_07.JPG	Unknown	Exterior of preserved watermill building	late C20	
VARIOUS07_08.JPG	Sussex: Polegate	New fantail for Polegate mill being built in workshop	late C20	
VARIOUS07_09.JPG	Unknown	Burnt out ruins of watermill	late C20	
VARIOUS07_10.JPG	Unknown	Burnt out ruins of watermill	late C20	
VARIOUS07_11.JPG	Unknown	Burnt out ruins of watermill	late C20	
VARIOUS07_12.JPG	Unknown	Burnt out ruins of watermill	late C20	
VARIOUS07_13.JPG	Unknown	Burnt out ruins of watermill	late C20	
VARIOUS07_14.JPG	Unknown	Burnt out ruins of watermill	late C20	
VARIOUS07_15.JPG	Bucks: Ivinghoe, Pitstone Green	Preserved post mill with sails	late C20	
VARIOUS07_16.JPG	Sussex: Shipley, King's Mill	Preserved smock mill with sails	late C20	
VARIOUS07_17.JPG	Cambs: Barnack	Preserved tower mill with cap and stocks	1970s	
VARIOUS08_01.JPG	Sussex: Bexhill, Downs Mill	Surviving trestle, roundhouse walls and wreckage of collapsed post mill	c1965-70	
VARIOUS08_02.JPG	Unknown	Exterior of preserved watermill building	late C20	Mill bears legend JENNER AND HIGGS AGRICULTURAL MERCHANTS, SEED & SEED CORN. Has appeared elsewhere in collection

VARIOUS08_03.JPG	Sussex: Battle, Caldbec Hill Mill	Tower of smock mill scaffolded for house conversion	late 60s/early 70s	
VARIOUS08_04.JPG	Sussex: Battle, Caldbec Hill Mill	Windshaft and some gearing of smock mill on ground	late 60s/early 70s	
VARIOUS08_05.JPG	Unknown	Empty wheelpit of watermill	late C20	
VARIOUS08_06.JPG	Unknown	Empty wheelpit of watermill	late C20	
VARIOUS08_07.JPG	Unknown	Ruined shell of watermill scaffolded for renovation	late C20	
VARIOUS08_08.JPG	Unknown	Ruined shell of watermill scaffolded for renovation	late C20	
VARIOUS08_09.JPG	Unknown	Interior of tower mill showing unidentified apparatus and timberwork	late C20	
VARIOUS08_10.JPG	Unknown	Interior of tower mill showing auxiliary steam drive(?)	late C20	
VARIOUS08_11.JPG	Unknown	Interior of tower mill showing governors	late C20	
VARIOUS08_12.JPG	Unknown	Interior of post mill roundhouse looking up at main post and crosstrees	late C20	
VARIOUS08_13.JPG	Norfolk: Weybourne	House-converted tower mill with sail frames	late C20	
VARIOUS08_14.JPG	Norfolk: Halvergate, High's Windpump	Derelect tower mill with cap, brakewheel and outriggers for tailpole: Howard's windpump, derelect tower mill with cap and two sails, is in background in distance	c1970	
VARIOUS08_15.JPG	Unknown	Exterior of watermill building with wheel, by river	late C20	
VARIOUS08_16.JPG	Sussex: St Leonards, Silverhill Mill	Smock mill under demolition: surviving base with some wreckage of smock on top	c1966	
VARIOUS08_17.JPG	Terwick watermill Trotton West Sussex	2 millers outside mill: Ayling brothers?	late C20	
VARIOUS08_18.JPG	Unknown	Remains of demolished watermill showing upright shaft, great spur wheel and other gearing	late C20	
VARIOUS08_19.JPG	Unknown	Interior of watermill under demolition showing upright shaft and crown wheel	late C20	
VARIOUS08_20.JPG	Unknown	Interior of watermill showing partly submerged pitwheel	late C20	
VARIOUS09_01.JPG	Unknown	Part of exterior of watermill building showing flooded area: probably mill in previous image	late C20	
VARIOUS09_02.JPG	Aberdeenshire?	Small stone watermill building with kiln	late C20	
VARIOUS09_03.JPG	Unknown	Interior of watermill showing wood/iron waterwheel with curved breastwork	late C20	
VARIOUS09_04.JPG	Unknown	Interior of watermill(?) building showing iron bevel gear	late C20	
VARIOUS09_05.JPG	Aberdeenshire?	Part of exterior of stone watermill building showing start & awe wheel	late C20	

VARIOUS09_06.JPG	Mill of Hirn, Aberdeenshire	Exterior of stone watermill building with oast house cowling for kiln on top	late C20	
VARIOUS09_07.JPG	Aberdeenshire?	Part of exterior of stone watermill building showing start & awe wheel	late C20	
VARIOUS09_08.JPG	Aberdeenshire?	Exterior of small stone building, presumably watermill	late C20	
VARIOUS09_09.JPG	Aberdeenshire, Auchendryne	Exterior of disused watermill building, with wheel, beside River Clunie	late C20	
VARIOUS09_10.JPG	Nether Alderley, Cheshire	Exterior of preserved watermill building	late C20	
VARIOUS09_11.JPG	Nether Alderley, Cheshire	Exterior of preserved watermill building	late C20	
VARIOUS09_12.JPG	Sussex: Angmering, Ecclesden Mill	Capless tower mill shell just prior to start of house conversion	c1973	
VARIOUS09_13.JPG	Sussex: Angmering, Ecclesden Mill	Capless tower mill shell just prior to start of house conversion	c1973	
VARIOUS09_14.JPG	Unknown	Fan boss, winding gear and part of fanstage of tower or smock mill	late C20	
VARIOUS09_15.JPG	Sussex: Pulborough, Nutbourne	Inside derelict tower mill looking up at windshaft, stocks (which have fallen across top of tower), and remains of cap frame; iron gearwheel also visible	c1970	Not sure if any other photo in the collection shows the unusual mounting for the brakewheel
VARIOUS09_16.JPG	Unknown	Vernacular building, presumably watermill, undergoing repair	late C20	
VARIOUS09_17.JPG	Unknown	Interior of watermill, looking up at great spur wheel, wallower and floor framing	late C20	
VARIOUS09_18.JPG	Unknown	Interior of watermill showing two pairs of stones, upright shaft and crown wheel	late C20	
VARIOUS09_19.JPG	Unknown	Interior of watermill showing detail of gearing	late C20	
VARIOUS09_20.JPG	Unknown	Interior of watermill in 09_17, showing detail of great spur wheel and floor framing	late C20	
VARIOUS10_01.JPG	Unknown	Bin floor of post mill showing detail of roof framing	late C20	
VARIOUS10_02.JPG	Unknown (poss. Woodchurch, Kent)	Interior of smock mill cap showing winding gear	late C20	
VARIOUS10_03.JPG	Unknown (poss. Woodchurch, Kent)	Dust floor of smock mill showing detail of curb, framing and truck wheel	late C20	
VARIOUS10_04.JPG	Unknown (poss. Woodchurch, Kent)	Dust floor of smock mill showing detail of curb, framing and truck wheel	late C20	
VARIOUS10_05.JPG	Kent: Woodchurch, Lower Mill	Derelict smock mill with cap and stocks	c1970	
VARIOUS10_06.JPG	Sussex: Hunston	smock mill in w/o, with house	late C19 or early C20	Not sure if any other photo in the collection shows this mill in w/o

VARIOUS10_07.JPG	Unknown	Interior of watermill showing pit wheel, wallower, great spur wheel and stone nut	late C20	
VARIOUS10_08.JPG	Unknown	interior of watermill showing chain cog lifting gear	late C20	
VARIOUS10_09.JPG	Unknown	Inside cap of tower mill showing b/w and windshaft	late C20	poss. Norfolk (slender windshaft)
VARIOUS10_10.JPG	Isle of Wight: Bembridge	Interior of tower mill showing wooden compass-arm great spur wheel and countershaft	late C20	
VARIOUS10_11.JPG	Isle of Wight: Bembridge	Interior of tower mill showing wooden lighter staff and part of great spur wheel	late C20	
VARIOUS10_12.JPG	Isle of Wight: Bembridge	Interior of tower mill showing wire machine	late C20	
VARIOUS10_13.JPG	Isle of Wight: Bembridge	Worm drive to cap from chainwheel	late C20	
VARIOUS10_14.JPG	Isle of Wight: Bembridge	Interior of cap of tower mill showing windshaft and brakewheel	late C20	
VARIOUS10_15.JPG	Isle of Wight: Bembridge	wooden lighter staff (as 10_11)	late C20	
VARIOUS11_01.JPG	Sussex: Mayfield, Argos Hill	New stock being fitted by Holes	late C20	
VARIOUS11_02.JPG	Unknown	Common sail frame at dusk	late C20	
VARIOUS11_03.JPG	Lincs: Wrawby	Post mill in w/o	late 1960s/early 70s	
VARIOUS11_04.JPG	Lincs: Wrawby	Post mill in w/o with working traction engine, driving thresher, in foreground	late 1960s/early 70s	
VARIOUS11_05.JPG	Lincs: Wrawby	Post mill in w/o	late 1960s/early 70s	
VARIOUS11_06.JPG	Essex: Orsett, Baker Street	Derelict smock mill with brakewheel and one sail	c1970?	
VARIOUS11_07.JPG	Norfolk: East Dereham, Cherry Lane	Derelict tower mill with windshaft and brakewheel	c1970?	
VARIOUS11_08.JPG	Northern Ireland?	Capless stone tower mill	late C20	
VARIOUS11_09.JPG	South Devon/Cornwall	Exterior of double watermill building with large single wheel between the two wings	late C20	This view has occurred elsewhere in the collection
VARIOUS11_10.JPG	South Devon/Cornwall	Exterior of double watermill building with large single wheel between the two wings	late C20	Same mill as in previous image
VARIOUS11_11.JPG	South Devon/Cornwall	Exterior of double watermill building with large single wheel between the two wings	late C20	Same mill as in previous image
VARIOUS11_12.JPG	Unknown	open fire with kettle in stable	late C20	Mill relevance?
VARIOUS11_13.JPG	Unknown	Exterior of thatched stone watermill building with breastshot wheel	late C20	
WATERMILL01_01	Unknown	Exterior of part brick, part weatherboarded watermill building; roof boards missing so may be under demolition/repair	late C20	

WATERMILL01_02	Unknown	Interior of watermill showing detail of flooring	late C20	
WATERMILL01_03	Unknown	arched doorway	late C20	
WATERMILL01_04	Unknown	Interior of watermill showing detail of flooring and brick support columns for main beams	late C20	
WATERMILL01_05	Unknown	Roof structure of unidentified building which appears to be under construction	late C20	
WATERMILL01_06	Unknown	Roof structure of unidentified building which appears to be under construction	late C20	
WATERMILL01_07	Unknown	Millstone and wooden gearwheel on ground	late C20	
WATERMILL01_08	Unknown	Millstone and wooden gearwheel on ground (same site as previous image)	late C20	
WATERMILL01_09	Unknown	Wooden gearwheel and shaft on ground (same site as previous image)	late C20	
WATERMILL01_10	Devon: Sticklepath, Finch Foundry	guillotine & forge hammers (picture very dark)	late C20	
WATERMILL01_11	Devon: Sticklepath, Finch Foundry	guillotine & forge hammers (picture very dark)	late C20	
WATERMILL01_12	Hants: A272 near Petersfield [Bramdean ?]	Large tiled barn	late C20	Visited on a Sussex mills tour: ask Peter Hill
WATERMILL01_13	Hants: A272 near Petersfield [Bramdean ?]	Pulley and shafting in barn roof	late C20	Visited on a Sussex mills tour: ask Peter Hill
WATERMILL01_14	Hants: A272 near Petersfield [Bramdean ?]	Pulley and shafting in barn roof	late C20	Visited on a Sussex mills tour: ask Peter Hill
WATERMILL01_15	Hants: A272 near Petersfield [Bramdean ?]	Pulley half buried in ground outside barn	late C20	Visited on a Sussex mills tour: ask Peter Hill
WATERMILL02_01	USA?	Exterior of preserved watermill building	late C20	
WATERMILL02_02	USA?	Exterior of preserved watermill building with wheel	late C20	
WATERMILL02_03	USA?	Interior of watermill building showing mashing barrel and associated gearing	late C20	
WATERMILL02_04	USA?	Interior of watermill building showing carding set	late C20	
WATERMILL02_05	USA?	water flowing alongside watermill	late C20	
WATERMILL02_06	USA?	Interior of watermill building showing millstones	late C20	
WATERMILL02_07	USA?	Interior of watermill building showing sawbench	late C20	
WATERMILL02_08	USA?	Interior of watermill building showing unidentified shaft and large gearwheel	late C20	
WATERMILL02_09	USA?	Preserved watermill building with weir	late C20	
WATERMILL02_10	USA?	Part of exterior of preserved watermill building with wheel	late C20	
WATERMILL02_11	USA?	Part of exterior of preserved watermill building with wheel	late C20	

[illegible]