

FWG-03116	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
CHRON 24_01	Mediterranean region	Unidentified, very low and small structure with tiled roof which is presumably watermill	late C20	
CHRON 24_02	Mediterranean region	Unidentified structure which is presumably watermill	late C20	
CHRON 24_03	Mediterranean region	Unidentified structure which is presumably watermill	late C20	
CHRON 24_04	Mediterranean region	Unidentified structure which is presumably watermill	late C20	
CHRON 24_05	Foreign	Interior of watermill showing two pairs of stones with hoppers	late C20	
CHRON 24_06	Foreign	Interior of watermill showing two pairs of stones with hoppers, plus third millstone on floor	late C20	
CHRON 24_07	Foreign	Interior of Norse-type watermill showing wheel	late C20	
CHRON 24_08	Foreign	Interior of Norse-type watermill showing wheel	late C20	
CHRON 24_09	Foreign	Interior of Norse-type watermill showing channel to wheel	late C20	
CHRON 24_10	Foreign	Interior of watermill showing two pairs of stones with hoppers	late C20	
CHRON 24_11	Mediterranean region	Unidentified, very low and small structure with tiled roof which is presumably watermill	late C20	
CHRON 24_12	Mediterranean region	Unidentified structure which is presumably watermill	late C20	
CHRON 24_13	Mediterranean region	Street scene	late C20	No apparent mill relevance
CHRON 24_14	Mediterranean region	Street scene	late C20	No apparent mill relevance
CHRON 24_15	Mediterranean region	Street scene	late C20	No apparent mill relevance
CHRON 24_16	Foreign	Interior of watermill showing two pairs of stones with hoppers and meal chests(?)	late C20	
CHRON 24_17	Foreign	Interior of watermill showing two pairs of stones with hoppers and unidentified large machine	late C20	Same mill as previous view
CHRON 25_01	Foreign	Landscape scene	late C20	No apparent mill relevance
CHRON 25_02	Foreign	Metal US-type windpump	late C20	
CHRON 25_03	Foreign	Metal US-type windpump	late C20	
CHRON 25_04	Foreign	Landscape scene	late C20	No apparent mill relevance
CHRON 25_05	Foreign	Landscape scene with small building in centre which is possibly watermill	late C20	
CHRON 25_06	Foreign	Rural scene	late C20	No apparent mill relevance
CHRON 25_07	Foreign	Blurred photo of what is presumably interior of watermill, showing pair of hoppers	late C20	
CHRON 25_08	Foreign	Interior of what is presumably watermill showing pair of hoppers	late C20	Same mill as previous view
CHRON 25_09	Foreign	Scene in wood	late C20	No mill relevance
CHRON 26_01	Foreign	Townscape	late C20	No mill relevance
CHRON 26_02	Foreign	Unidentified structure which is presumably watermill	late C20	
CHRON 26_03	Foreign	Quern	late C20	
CHRON 26_04	Foreign	Interior of watermill showing two pairs of stones with hoppers and meal chests(?)	late C20	Same mill as shown previously
CHRON 26_05	Foreign	Quern	late C20	
CHRON 26_06	Mediterranean region	Pair of wooden smock-type windmills, one with bowsprit and remains of sails	late C20	

FWG-03116	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
CHRON 26_07	Mediterranean region	Interior of what is presumably windmill, showing solid wood gearwheel straked to wooden shaft	late C20	
CHRON 26_08	Mediterranean region	Interior of what is presumably windmill, showing detail of framing and lantern pinion gearwheel	late C20	
CHRON 26_09	Mediterranean region	Unidentified tower-like structure with bowsprit like that found on the windmills of the region	late C20	
CHRON 26_10	Mediterranean region	Interior of windmill showing wooden gearing including lantern pinion stone nut	late C20	
CHRON 26_11	Foreign	Coastal scene	late C20	
CHRON 26_12	Foreign	Coastal scene with unidentified man	late C20	
CHRON 26_13	Mediterranean region	Man setting cloths on rotatable smock-type windmill which stands on wooden base	late C20	
CHRON 26_14	Mediterranean region	pair of thatched houses	late C20	No mill relevance
CHRON 26_15	Mediterranean region	Rotatable smock-type windmill on masonry base with conical cap, bowsprit and jib sails	late C20	
CHRON 26_16	Mediterranean region	Winch for turning above mill	late C20	
CHRON 27_01	Mediterranean region	Old photo showing curious structure which is presumably part of watermill	late C19 or early C20	
CHRON 27_02	Mediterranean region	Old photo showing curious structure which is presumably part of watermill	late C19 or early C20	
CHRON 27_03	UK	Small derelict watermill building	late C20	
CHRON 27_04	UK, poss. Faversham, Chart Mills		late C20	
CHRON 27_05	UK, poss. Faversham, Chart Mills	Excavated site of water-powered industrial complex with positions of mills indicated	late C20	
CHRON 27_06	UK, poss. Faversham, Chart Mills	Excavated site of water-powered industrial complex with positions of mills indicated	late C20	
CHRON 27_07	UK, poss. Faversham, Chart Mills	Excavated site of water-powered industrial complex with positions of mills indicated	late C20	
CHRON 27_08	UK, poss. Faversham, Chart Mills	Excavated site of water-powered industrial complex with positions of mills indicated	late C20	
CHRON 27_09	UK	Part of exterior of derelict watermill building showing wheel axle (wheel gone)	late C20	
CHRON 27_10	UK	Interior of watermill showing u/s, wallower and gsw	late C20	
CHRON 27_11	UK	Interior of watermill showing gsw s/nut and quant	late C20	
CHRON 27_12	UK	Interior of watermill showing pit wheel, wallower and gsw	late C20	
CHRON 27_13	UK	Interior of watermill showing pit wheel, wallower and gsw	late C20	
CHRON 27_14	UK	Part of exterior of derelict watermill building	late C20	
CHRON 27_15	UK	Interior of watermill showing upright shaft and crown wheel	late C20	

FWG-03116	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
CHRON 27_16	UK	Bin floor of watermill	late C20	
CHRON 27_17	Sussex: Fletching	Piece of cloth bearing legend "JOSEPH MARTIN FLETCHING MILL"	late C20	
CHRON 27_18	UK	View of bin floor of derelict watermill	late C20	
CHRON 27_19	Sussex: prob. Clayton, "Jill" mill	Interior of post mill roundhouse showing main post, quarterbars, collar and sheers	late C20	
CHRON 27_20	Sussex: prob. Clayton, "Jill" mill	Interior of post mill roundhouse showing main post, quarterbars, collar and sheers	late C20	
CHRON 28_01	Unknown	Remains of large gearwheel on ground	late C20	
CHRON 28_02	Sussex: Clayton, "Jill" post mill and "Jack" tower mill	Restored post mill with sail frames (shutters not yet fitted); restored tower mill with sail frames in background	1980s	
CHRON 28_03	Sussex: Clayton, "Jill" post mill	Man pushing round sails of restored post mill, to which some shutters have been fitted	1980s	
CHRON 28_04	Sussex: Clayton, "Jill" post mill	Man working on sails of restored post mill, to which some shutters have been fitted	1980s	
CHRON 28_05	Sussex: Clayton, "Jill" post mill	Restored post mill with some shutters fitted to sails	1980s	
CHRON 28_06	Sussex: Clayton, "Jill" post mill	Fantail, fan carriage and winding gear of restored post mill	1980s	
CHRON 29_01	Sussex: Clayton, "Jill" post mill	Interior of post mill under restoration, showing main post, crowntree, tailwheel and auxiliary/sack hoist drive	1980s	
CHRON 29_02	Sussex: Clayton, "Jill" post mill	Interior of post mill under restoration, showing main post and crowntree	1980s	
CHRON 29_03	Sussex: Clayton, "Jill" post mill	Interior of post mill under restoration, showing wire machine and associated gearing	1980s	
CHRON 29_04	Sussex: Clayton, "Jill" post mill	Interior of post mill under restoration, showing main post and crowntree	1980s	
CHRON 29_05	Sussex: Clayton, "Jill" post mill	Interior of post mill under restoration, showing decayed timberwork	1980s	
CHRON 29_06	Sussex: Clayton, "Jill" post mill	Interior of post mill under restoration, showing decayed timberwork	1980s	
CHRON 29_07	Sussex: Clayton, "Jill" post mill	Post mill under restoration, with new sail frames recently fitted	early-mid 1980s	
CHRON 29_08	Sussex: Clayton, "Jill" post mill	Post mill under restoration, with new sail frames recently fitted	early-mid 1980s	
CHRON 29_09	Sussex: Clayton, "Jill" post mill	Fantail, fan carriage and winding gear of restored post mill	1980s	
CHRON 29_10	Sussex: Clayton, "Jill" post mill	Fantail, fan carriage and winding gear of restored post mill	1980s	
CHRON 29_11	Unknown	Interior of watermill(?) showing set of C19/early C20 roller mills	late C20	

FWG-03116	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
CHRON 29_12	Unknown	Painting showing half-timbered watermill building with wheel, by pond	C18/19	
CHRON 29_13	Sussex: Devil's Dyke, near Brighton	Waterwheel-like structure, apparently standing alone	late C19 or early C20	Picture (evidently postcard) is captioned "The Devil's Wheel"
CHRON 29_14	Sussex: Devil's Dyke, near Brighton	Waterwheel-like structure, apparently standing alone	late C19 or early C20	Picture (evidently postcard) is captioned "The Devil's Wheel"
CHRON 29_15	Sussex: Devil's Dyke, near Brighton	Waterwheel-like structure, apparently standing alone	late C19 or early C20	Picture (evidently postcard) is captioned "The Devil's Wheel"
CHRON 30_01	UK	modern wind turbine with cooling towers of power station in background	late C20	
CHRON 30_02	UK	modern wind turbine with cooling towers of power station in background	late C20	
CHRON 30_03	Sussex	Model of wind turbine in exhibition centre	late C20	
CHRON 30_04	Sussex	Model of wind turbine in exhibition centre	late C20	
CHRON 30_05	Sussex	Models of modern wind turbine and traditional windmills in exhibition centre	late C20	
CHRON 30_06	Sussex	Models of modern wind turbines in exhibition centre	late C20	
CHRON 30_07	Sussex	Pair of stone nuts from traditional windmill/watermill, one iron and one solid wood	late C20	
CHRON 30_08	Sussex	Pair of stones with furniture, collection of mill bills and other traditional windmilling items in exhibition centre	late C20	
CHRON 30_09	Sussex	Model of the Bishopstone windmill and tide mills in exhibition centre	late C20	
CHRON 30_10	Sussex	Model of the Bishopstone windmill and tide mills in exhibition centre	late C20	
CHRON 30_11	Sussex	Model of the Bishopstone windmill and tide mills in exhibition centre	late C20	
CHRON 30_12	Sussex	Model of watermill in display case at exhibition centre	late C20	
CHRON 30_13	Sussex	TV on in darkened room at exhibition centre	late C20	
CHRON 30_14	Sussex	models of watermill and the Bishopstone mills at exhibition centre	late C20	
CHRON 30_15	Sussex	Display cases and diagrams at exhibition centre	late C20	
CHRON 30_16	Sussex	Model of post mill, section of spring sail with spring, and other items in exhibition centre	late C20	
CHRON 30_17	Sussex	painting of post mill in w/o in downland landscape, very detailed and probably accurate	C19 or early C20	Mill needs identifying
CHRON 31_01	Sussex	Model of post mill, section of spring sail with spring, and other items in exhibition centre	late C20	
CHRON 31_02	Sussex	Blade of fantail and other items in exhibition centre	late C20	
CHRON 31_03	Sussex: Washington, Rock Mill	Painting showing smock mill in w/o	C19 or early C20	

FWG-03116	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
CHRON 31_04	Unknown	Poorly reproduced painting	?	
CHRON 31_05	Sussex: Eastbourne, Ocklynge Mill	poorly reproduced painting showing tower mill in w/o	early C20?	This is the view in A Foord Hughes
CHRON 31_06	Sussex: Eastbourne, Ocklynge Mill	poorly reproduced painting showing tower mill in w/o	early C20?	This is the view in A Foord Hughes
CHRON 31_07	Sussex	Items in display cases at exhibition centre	late C20	
CHRON 31_08	Sussex	Items in display cases at exhibition centre	late C20	
CHRON 31_09	Sussex	Items in display cases at exhibition centre	late C20	
CHRON 31_10	Sussex	Items in display cases at exhibition centre	late C20	
CHRON 31_11	Sussex	Items in display cases at exhibition centre	late C20	
CHRON 31_12	Unknown	Painting showing US-type windpump	C20	
CHRON 31_13	Sussex: Clayton, "Jill" post mill and "Jack" tower mill	Snow scene showing tower and post mill, both restored with sail frames	1980s	
CHRON 31_14	Sussex: Clayton, "Jill" post mill	Snow scene showing post mill restored with sail frames	1980s	
CHRON 31_15	Sussex: Clayton, "Jill" post mill	Snow scene showing post mill restored with sail frames	1980s	
CHRON 32_01	Sussex: Herstmonceux, Windmill Hill	Snow scene showing derelict post mill without sails	1980s	
CHRON 32_02	Sussex: Herstmonceux, Windmill Hill	Snow scene showing derelict post mill without sails	1980s	
CHRON 32_03	Sussex: Herstmonceux, Windmill Hill	Snow scene showing derelict post mill without sails	1980s	
CHRON 32_04	Sussex: Herstmonceux, Windmill Hill	Derelict post mill without sails	1980s	
CHRON 32_05	Sussex: Herstmonceux, Windmill Hill	Derelict post mill without sails	1980s	
CHRON 32_06	Oxon: Bloxham, Bloxham Grove	Restored open-trestle post mill with sails, painted white	1980s or 90s	
CHRON 32_07	Oxon: Bloxham, Bloxham Grove	Restored open-trestle post mill with sails, painted white	1980s or 90s	
CHRON 32_08	Unknown	Large watermill building, apparently still in use as industrial premises	late C20	
CHRON 32_09	Unknown	Large watermill building, apparently still in use as industrial premises	late C20	
CHRON 32_10	Unknown	Large watermill building, apparently still in use as industrial premises	late C20	Same mill as in previous 2 views
CHRON 32_11	Unknown	Small rural building	late C20	Mill relevance?
CHRON 32_12	WADOAM Singleton?	Unidentified structure made out of interwoven branches	late C20	Mill relevance?
CHRON 32_13	WADOAM Singleton?	Reconstructed Iron Age (?) dwelling	late C20	No mill relevance
CHRON 32_14	WADOAM Singleton?	Tollkeeper's cottage	late C20	No mill relevance
CHRON 32_15	WADOAM Singleton?	Pair of traditional rural buildings	late C20	Mill relevance?
CHRON 32_16	WADOAM Singleton?	the pair of traditional rural buildings and the tollkeeper's cottage	late C20	Mill relevance?
CHRON 32_17	WADOAM Singleton?	Traditional building under reconstruction	late C20	Mill relevance?
CHRON 32_18	WADOAM Singleton?	Pair of traditional rural buildings	late C20	No mill relevance
CHRON 33_01	WADOAM Singleton?	Interior of traditional rural building	late C20	No mill relevance
CHRON 33_02	Unknown	Half-timbered red brick house in village street	late C20	No mill relevance
CHRON 33_03	Unknown	Scene at preserved steam railway	late C20	No mill relevance
CHRON 33_04	Unknown	Scene at industrial museum showing oil derrick(?) and pithead wheel	late C20	No mill relevance

FWG-03116	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
CHRON 33_05	Unknown	Scene at industrial museum showing inclined railway	late C20	No mill relevance
CHRON 33_06	Unknown	Preserved stationmaster's house(?)	late C20	No mill relevance
CHRON 33_07	Unknown	Preserved vernacular building	late C20	No mill relevance
CHRON 33_08	Unknown	Scene at open-air museum(?) showing factory-like building with chimney and vernacular building in course of repair/reconstruction	late C20	No mill relevance
CHRON 33_09	Unknown	View inside factory-like building showing limekiln(?)	late C20	No mill relevance
CHRON 33_10	Unknown	View inside factory-like building showing modern(?) machinery	late C20	No mill relevance
CHRON 33_11	Unknown	Inclined railway and bridge	late C20	No mill relevance
CHRON 33_12	Unknown	stained-glass window in church	late C20	Mill relevance?
CHRON 33_13	Unknown	stained-glass window in church	late C20	Mill relevance?
CHRON 34_01	Sussex: Herstmonceux, Windmill Hill	Derelict post mill without sails	1980s or early 90s	
CHRON 34_02	Sussex: West Blatchington	Preserved smock mill with sails, scaffolded for repairs	late C20	
CHRON 34_03	Sussex: West Blatchington	Preserved smock mill with sails, scaffolded for repairs	late C20	
CHRON 34_04	Prob. Sussex, West Blatchington	Millstone leaning against wall of brick and flint structure scaffolded for repairs	late C20	
CHRON 34_05	Unknown	Interior of watermill showing flour dresser and auxiliary gearing	late C20	
CHRON 34_06	Unknown	Interior of watermill showing flour dresser and auxiliary gearing	late C20	
CHRON 34_07	Sussex: Keymer, Oldland Mill	Post mill in w/o, with sails draped with Union Jack flags	late C19 or early C20	Occasion being celebrated is probably (a) Queen Victoria's Diamond Jubilee 1897; (b) coronation of Edward VII 1902; or © coronation of George V 1911
CHRON 34_08	Sussex: Keymer, Oldland Mill	Post mill in w/o, with sails draped with Union Jack flags	late C19 or early C20	Occasion being celebrated is probably (a) Queen Victoria's Diamond Jubilee 1897; (b) coronation of Edward VII 1902; or © coronation of George V 1912
CHRON 34_09	Sussex: Keymer, Oldland Mill	Post mill in w/o, with sails draped with Union Jack flags	late C19 or early C20	Occasion being celebrated is probably (a) Queen Victoria's Diamond Jubilee 1897; (b) coronation of Edward VII 1902; or © coronation of George V 1913
CHRON 34_10	Sussex: Keymer, Oldland Mill	Post mill in w/o, with sails draped with Union Jack flags	late C19 or early C20	Occasion being celebrated is probably (a) Queen Victoria's Diamond Jubilee 1897; (b) coronation of Edward VII 1902; or © coronation of George V 1914
CHRON 34_11	Sussex: Keymer, Oldland Mill	Post mill in w/o	late C19 or early C20	
CHRON 34_12	Sussex: Herstmonceux, Windmill Hill	Derelict post mill without sails	1980s or early 90s	
CHRON 34_13	Sussex: Herstmonceux, Windmill Hill	Derelict post mill without sails	1980s or early 90s	
CHRON 34_14	Sussex: Herstmonceux, Windmill Hill	Derelict post mill without sails	1980s or early 90s	

FWG-03116	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
CHRON 34_15	Sussex: Herstmonceux, Windmill Hill	Derelict post mill without sails	1980s or early 90s	
CHRON 35_01	Unknown	Interior of watermill showing modern milling machine (resembles pair of stones with hopper)	late C20	
CHRON 35_02	Unknown	Interior of watermill, apparently working, showing pair of stones with hopper	late C20	Probably same mill as in previous view
CHRON 35_03	Unknown	Interior of watermill showing unidentified machine and associated gearing	late C20	Probably same mill as in previous view
CHRON 35_04	Unknown	Interior of watermill showing man supervising feed to pair of stones	late C20	Same mill as in previous views
CHRON 35_05	Unknown	Interior of watermill showing modern steel hoppers	late C20	Same mill as in previous views
CHRON 35_06	Unknown	Bin floor of watermill showing sack hoist	late C20	
CHRON 35_07	Unknown	Bin floor of watermill showing sack hoist	late C20	
CHRON 35_08	Unknown	Bin floor of watermill	late C20	
CHRON 35_09	Unknown	Bin floor of watermill showing modern chute and tanks	late C20	
CHRON 35_10	Unknown	Part of exterior of watermill building showing shed-like structure over watercourse	late C20	
CHRON 35_11	Prob. East Anglia	Interior of watermill(?) showing gearing inside iron hurst frame	late C20	Cast inscription says "R GARRETT & SONS LEISTON WORKS SUFFOLK ENGLAND"
CHRON 35_12	Unknown	Interior of watermill(?) showing sluice gate controls(?)	late C20	
CHRON 35_13	Sussex: Lewes, St Anne's Churchyard	Row of iron grave markers for Medhurst family	late C20	
CHRON 35_14	Sussex: Clayton, "Jill" Mill	Post mill restored to w/o	late C20	
CHRON 35_15	Sussex: Clayton, "Jill" Mill	Post mill restored to w/o	late C20	Sails dressed with bunting
CHRON 35_16	Sussex: Clayton, "Jill" Mill	Post mill restored to w/o	late C20	Sails dressed with bunting
CHRON 35_17	Sussex: Clayton, "Jill" Mill	Post mill restored to w/o	late C20	Sails dressed with bunting
CHRON 35_18	Sussex: Clayton, "Jill" Mill	Post mill restored to w/o	late C20	Sails dressed with bunting
CHRON 35_19	Sussex: Clayton, "Jill" Mill	Post mill restored to w/o: close-up of sails and striking gear	late C20	Sails dressed with bunting
CHRON 36_01	Unknown	Scene at open-air museum(?), showing site of building awaiting construction	late C20	Mill relevance?
CHRON 36_02	Unknown	Tollkeeper's cottage	late C20	No mill relevance
CHRON 36_03	Unknown	Small horse mill and associated gearing in grounds of unidentified building	late C20	
CHRON 36_04	Unknown	Small horse mill and associated gearing in grounds of unidentified building	late C20	
CHRON 36_05	Unknown	Photo of display plaque concerning John Smeaton and his work	late C20	
CHRON 36_06	Unknown	Interior of watermill showing stone weight on chain	late C20	Poor view, mostly in shadow
CHRON 36_07	Unknown	Interior view of watermill showing what appear to be bevel gears	late C20	Poor view, mostly in shadow
CHRON 36_08	Unknown	Interior view of watermill showing part of wheel	late C20	Poor view, mostly in shadow
CHRON 36_09	Unknown	interior view of watermill showing unidentified mechanism	late C20	Poor view, mostly in shadow
CHRON 36_10	Staffordshire: Forton	Partly collapsed stone tower of possible windmill (could be a folly)	late C20	

FWG-03116	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
CHRON 36_11	Staffordshire: Forton	Partly collapsed stone tower of possible windmill (could be a folly)	late C20	
CHRON 36_12	Unknown	Man working unidentified machine to/from which a belt is passing through the window of unidentified building (watermill?)	late C20	
CHRON 36_13	Unknown	Man working unidentified machine to/from which a belt is passing through the window of unidentified building (watermill?)	late C20	
CHRON 36_14	Unknown	Man working unidentified machine to/from which a belt is passing through the window of unidentified building (watermill?)	late C20	
CHRON 36_15	Unknown	Part of exterior of watermill building showing waterwheel seen through hatch in wall	late C20	
CHRON 36_16	Unknown	Part of exterior of watermill building showing waterwheel seen through opening in wall	late C20	
CHRON 36_17	Unknown	Man working unidentified machine resembling a cross between press and bellows	late C20	
CHRON 37_01	Unknown	Exterior of preserved watermill building showing wheel	late C20	Same mill as 36_16
CHRON 37_02	Sussex: Icklesham, Hog Hill	Post mill scaffolded for repair, with stocks and roof fantail in place	1980s	
CHRON 37_03	Sussex: Icklesham, Hog Hill	Post mill scaffolded for repair, with stocks and roof fantail in place	1980s	
CHRON 37_04	Sussex: Icklesham, Hog Hill	Post mill scaffolded for repair, with stocks and roof fantail in place	1980s	
CHRON 37_05	Sussex: Clayton, "Jack" tower mill	Underground passage connecting mill with house	late C20	
CHRON 37_06	Sussex: Clayton, "Jack" tower mill	Lowermost section of upright shaft showing dummy floor which supports it, and iron supporting column underneath	late C20	
CHRON 37_07	Sussex: Clayton, "Jack" tower mill	Chapel on stone floor, with upright shaft to right	late C20	
CHRON 37_08	Sussex: Clayton, "Jack" tower mill	Interior of cap showing windshaft	late C20	
CHRON 37_09	Sussex: Clayton, "Jack" tower mill	Interior of cap showing windshaft, cap frame, truck wheels, sprattle beam and top of upright shaft	late C20	
CHRON 37_10	Sussex: Clayton, "Jack" tower mill	Looking down onto dust floor from cap frame	late C20	
CHRON 37_11	Sussex: Clayton, "Jack" tower mill	Cap frame, truck wheels and tail of windshaft	late C20	
CHRON 37_12	Sussex: Clayton, "Jack" tower mill	Cap frame and truck wheels: also shows detail of cap roof framing	late C20	
CHRON 37_13	Sussex: Clayton, "Jack" tower mill	View of bin(?) floor showing part of upright shaft	late C20	
CHRON 37_14	Sussex: Clayton, "Jack" tower mill	View of bin(?) floor showing upright shaft	late C20	
CHRON 37_15	Sussex: Clayton, "Jack" tower mill	Section of flooring	late C20	
CHRON 37_16	Sussex: Clayton, "Jack" tower mill	Underground passage connecting mill with house	late C20	

FWG-03116	Mill (county, location, mill name)	Title (short description of image)	Year	Notes/comments
CHRON 37_17	Unknown	Exterior of derelict watermill building	late C20	
CHRON 37_18	Unknown	Exterior of preserved watermill building	late C20	
CHRON 37_19	Unknown	Mill race	late C20	