

FWG-02514 GB5

Slide page/number	Mill (county, location, mill name)	Title (short description of image)	Date	Comments
AZORES 01_01	Azores	Small smock/tower mill typical of region, apparently in w/o	Oct-84	Shows wheels on which "smock" part rotates like a cap on a curb
AZORES 01_02	Azores	Small smock type mill on stone base, with Mediterranean-type jib sails	Oct-84	
AZORES 01_03	Azores	Small smock type mill on stone base, etc, with men standing on base and sails spread with cloth	Oct-84	
AZORES 01_04	Azores	Interior of windmill, prob. of the "smock" type, showing miller with brakewheel and single pair of stones	Oct-84	
AZORES 01_05	Azores/Portugal	Miller standing outside Portuguese-type tower mill with sails rigged	Oct-86	
AZORES 01_06	Azores/Portugal	Interior of wind- or watermill showing stone nut, quant and single pair of stones	Oct-86	
AZORES 01_07	Azores/Portugal	Interior of windmill showing miller standing by brakewheel and single pair of stones	Oct-86	
AZORES 01_08	Azores: Espanamara Faral?	Tower mill with conical cap, tailpole, battered tower and Med-type sails	Oct-81	
AZORES 01_09	Azores/Portugal	Small smock type mill on stone base, apparently disused, with sails in form of wooden cross	Oct-81	
AZORES 01_10	Azores	Tower mill with conical cap, common sails, bowsprit and access ladder leading to platform which is corporate with cap	Oct-81	
AZORES 01_11	Azores/Portugal	Disused smock-type mill on stone base, with stock for two common sails	Oct-81	
AZORES 01_12	Azores	Tower mill with ogee cap, common sails and tailpole, apparently preserved	Oct-81	

AZORES 01_13	Azores	Interior of wooden windmill showing brakewheel and single pair of stones on platform	Oct-81
AZORES 01_14	Azores/Portugal	Smock-type mill on stone base, etc, with Med-type bowsprit and sails	Oct-81
AZORES 01_15	Azores	Paving stones arranged to form windmill design	Oct-81
CAPECOD 01_01	Cape Cod(?), USA	Preserved smock mill with sails and tailpole	late C20
CAPECOD 01_02	Cape Cod(?), USA	Close-up of cap and sails of preserved smock mill	late C20
CAPECOD 01_03	Cape Cod(?), USA	Preserved smock mill with common sails spread (so evidently in w/o)	late C20
CAPECOD 01_04	Cape Cod(?), USA	Preserved smock mill with common sails spread	late C20
CAPECOD 01_05	Cape Cod(?), USA	Preserved smock mill with sails and tailpole	late C20
CAPECOD 01_06	USA: Maryland, Lloyds, Spocott Mill	Preserved open-trestle post mill with sails	Aug-75
CAPECOD 01_07	USA: Newport, Rhode Island, Eastham	Possible windmill tower built on arches as at Chesterton	Sep-75
CAPECOD 01_08	Cape Cod(?), USA	Preserved smock mill with common sails spread	Sep-75
CAPECOD 01_09	USA	Preserved smock mill with common sails spread	Sep-75
CAPECOD 01_10	USA: Rhode Island, Jamestown	Preserved smock mill with common sails spread	Sep-75
CAPECOD 01_11	USA: Easthampton, Hook Mill	Preserved smock mill with sails	Aug-75
CAPECOD 01_12	USA: Williamsburg	Preserved open-trestle post mill with common sails spread and apparently working	Aug-75
CAPECOD 01_13	USA	Smock mill with sails, incorporated into house	Jun-69
CAPECOD 01_14	USA	Part of old document concerning mill; begins "This mill was drawn on the 28th March 1797..."	Mar-68

CAPECOD 01_15	USA	Preserved smock mill with sails	Jun-69
CAPECOD 01_16	USA: Maryland, Lloyds, Spocott Mill	Preserved open-trestle post mill with sails	late C20 as 01_06
CAPECOD 01_17	Majorca	Modern-type windpump beside large stone structure with mountains in background	May-82
CAPECOD 01_18	Majorca	Derelict modern-type windwheel above large square structure	May-82
CAPECOD 01_19	Mediterranean region: Arcos de la Frontera, hotel "La Molinero"	Small tower mill with cap and dummy sails	Oct-72
CAPECOD 01_20	South Africa: Cape Town, Mostert's Mill	Preserved tower mill with sails and tailpole	May-68
DENMARK 01_01	Germany	Preserved smock mill with sails	Oct-82
DENMARK 01_02	Denmark/Germany	Preserved smock mill in working order; model mill in garden in foreground	Oct-82 More probably Germany
DENMARK 01_03	Germany (Schleswig Holstein)	Preserved smock mill in w/o	Jul-82
DENMARK 01_04	Denmark/Germany, Balbeck	Preserved smock mill with common sails and tailpole	Mar-74
DENMARK 01_05	Denmark	Derelict smock mill with fantail and one stock; other buildings nearby	late C20
DENMARK 01_06	Denmark/Germany	Close-up of shutters on sails of unidentified mill	Jul-82
DENMARK 01_07	Denmark/Germany	Close-up of shutters on sails of unidentified mill	Jul-82
DENMARK 01_08	Denmark, Dybol	Tower mill in working order	Jan-74
DENMARK 01_09	Denmark	Preserved open-trestle post mill with sails	Jul-82
DENMARK 01_10	Denmark	Preserved smock mill with sails and tailpole	Jul-82
DENMARK 01_11	Denmark	Preserved tower mill with sails	Jul-82
DENMARK 01_12	Denmark: Lolland, Kappel	Preserved open-trestle post mill with sails Group of five preserved open-trestle post mills by road	Jul-82
DENMARK 01_13	Sweden: Oland	Mills by road	Jan-74
DENMARK 01_14	Sweden: Sandvik, Oland	Preserved smock mill with sails	Jan-74

DENMARK 01_15	Sweden: Oland	Very small preserved open-trestle post mill with trestle buried within stone substructure	Jan-74
DENMARK 01_16	Prob. Sweden, Oland	View inside windmill showing windshaft, brakewheel and lantern pinion stone nut	Jan-74
DENMARK 01_17	Sweden, Oland	Post mill, apparently preserved, with sails and stone substructure	Jan-74
DENMARK 01_18	Sweden: Hogby, Oland	Preserved tower mill with sails	Jan-74
DRESSING 01_01	Unknown	Unidentified man dressing a stone	Feb-80 Scene taking place inside smock mill?
DRESSING 01_02	Unknown	Unidentified man dressing a stone	Feb-80 Scene taking place inside smock mill?
DRESSING 01_03	Unknown	Unidentified man dressing a stone	Feb-80 Scene taking place inside smock mill?
DRESSING 01_04	Unknown	Unidentified man dressing a stone	Feb-80 Scene taking place inside smock mill?
DRESSING 01_05	Unknown	Unidentified man dressing a stone	Feb-80 Scene taking place inside smock mill?
DRESSING 01_06	Unknown	Unidentified man dressing a stone	Feb-80 Scene taking place inside smock mill?
DRESSING 01_07	Unknown	Unidentified man dressing a stone	Feb-80 Scene taking place inside smock mill?
DRESSING 01_08	Sussex: Cross-in-Hand, New Mill	Derelict post mill without sails	Mar-83
DRESSING 01_09	Sussex: Clayton, "Jill" Mill	Post mill under repair, showing men in process of fitting/removing stock	Mar-83
DRESSING 01_10	Sussex: Clayton, "Jill" Mill	Post mill scaffolded for repair, with one stock in position	Mar-83
DRESSING 01_11	Unknown	Charred item of timberwork on ground	May-80
DRESSING 01_12	Norfolk: Upton, Palmer's Mill	Restored hollow-post windpump with sails not yet fitted: tower windpump with cap, prob. Clippesby mill, visible in background in distance	May-80
DRESSING 01_13	Norfolk:Wicklewood	Tower mill in course of repair, with flat roof over top; windshaft, brakewheel, new stocks and other items on ground	May-80

DRESSING 01_14	Essex: Thaxted Suffolk: Stowmarket, Museum of East Anglian Life, ex-East Bridge nr Leiston	Tower mill scaffolded for repair, with cap and sails in place	May-80
DRESSING 01_15	Suffolk: Saxtead Green	Restored smock windpump with sails	May-80
DRESSING 01_16	Suffolk: Saxtead Green	Restored post mill with sails	May-80
DRESSING 01_17	Suffolk: Saxtead Green	Restored post mill with sails	May-80
DRESSING 01_18	Norfolk: Horsford	Derelict tower mill with cap frame and windshaft	May-80
DRESSING 01_19	Norfolk: Clippesby	Preserved tower windpump without sails	May-80
DRESSING 01_20	Norfolk: Upton, Palmer's Mill	Restored hollow-post windpump with sails not yet fitted	May-80
DUTCHETC 01_01	France: Beauce region?	Restored tower mill with sails	Apr-82
DUTCHETC 01_02	France: Beauce region?	Restored tower mill with sails	Apr-82
DUTCHETC 01_03	Netherlands: Arnhem Open-Air Museum	Tjasker windpump and large corn tower mill	May-73
DUTCHETC 01_04	France: Beauce region?	Derelict(?) open-trestle post mill with sails	Apr-82
DUTCHETC 01_05	France	Preserved "cavier" hollow-post mill	Apr-82
DUTCHETC 01_06	France	Preserved "cavier" hollow-post mill	Sep-74
DUTCHETC 01_07	France: Brittany, "Devil's Mill"	Preserved tower mill with sails	Sep-74
DUTCHETC 01_08	Foreign	View inside windmill showing brakewheel, wallower and upright shaft	Jul-85
DUTCHETC 01_09	Netherlands	Preserved post mill with common sails spread and turning	Jul-85
DUTCHETC 01_10	France/Belgium	Preserved post mill with two common sails spread and turning	Jul-85
DUTCHETC 01_11	Netherlands/Germany	Preserved smock mill with two sails	Jul-85
DUTCHETC 01_12	Netherlands	Pair of edge runner stones within industrial windmill	Jul-85
DUTCHETC 01_13	Netherlands	Preserved tower mill with two sails spread with canvas	Jul-85
DUTCHETC 01_14	Netherlands	Unidentified man dressing a stone	Jul-85
DUTCHETC 01_15	Netherlands: Kinderdijk	Row of preserved smock drainage mills with sails turning	May-73

Mill has pannier on one side of body

DUTCHETC 01_16	Netherlands: Kinderdijk	Row of 13 preserved drainage mills (12 smock and one polder) in distance with sails turning	May-73	
DUTCHETC 01_17	Netherlands	Pair of preserved open-trestle post mills by swing bridge by river	May-79	
DUTCHETC 01_18	Netherlands	Preserved open-trestle post mill with sails	May-79	
DUTCHETC 01_19	Netherlands	Preserved polder mill with sails turning	May-73	
DUTCHETC 01_20	Netherlands, Middelburg	Preserved tower mill with sails by river	14th May 1957	
EUROMIX 01_01	UK: Somerset, Chapel Allerton, Ashton Mill	Preserved tower mill with sails	30th Oct 1959	
EUROMIX 01_02	Kent: Chillenden	Preserved open-trestle post mill with sails	16th May 1959	
EUROMIX 01_03	Prob. Mediterranean region	View inside windmill showing miller with brakewheel and single pair of stones	Oct-82	Whole mill seems built of masonry including roof section/cap
EUROMIX 01_04	Finland/Eastern Europe	Open-trestle post-type mill, probably within open-air museum	Oct-83	
EUROMIX 01_05	Derbyshire:South Normanton	Skeleton of post mill with post, trestle, main buck timbers and windshaft only remaining	Aug-72	
EUROMIX 01_06	Sussex: Cross-in-Hand, New Mill	Part of body and sail of post mill in w/o	Jun-69	
EUROMIX 01_07	Sussex: Cross-in-Hand, New Mill	Post mill following storm damage, with one sail on ground	Jun-69	
EUROMIX 01_08	Foreign	Painting of harbour scene with town and two tower mills, one with tailpole, in background	C18/C19	
EUROMIX 01_09	Mediterranean region	Row of about 8 derelict tower mills, one of conventional type with windshaft still in position, others in form of stone "houses" which remained stationary	Oct-82	
EUROMIX 01_10	Kent: Guston, Swingate Mill	Tower mill in w/o	late C19 or early C20	
EUROMIX 01_11	Kent: High Halden	Post mill in w/o	late C19 or early C20	

EUROMIX 01_12	Suffolk: Framsden	Post mill under repair, with fantail and one stock in place	c1970
EUROMIX 01_13	Somerset: Chapel Allerton, Ashton Mill	Preserved tower mill with sails	1970s
EUROMIX 01_14	Kent: Herne	Exposed (new?) cap roof framing of tower-type mill under repair, showing also brakewheel, windshaft and part of common sails+C125	late C20
FINMILL 01_01	Finland: Turku	Large preserved smock mill with sails	late C20
FINMILL 01_02	Finland	Preserved smock mill with sails and tailpole	late C20
FINMILL 01_03	Finland	Two preserved post/hollow-post mills, with sails, prob. in open-air museum	late C20
FINMILL 01_04	Finland	Preserved post/hollow-post mill with sails	late C20
FINMILL 01_05	Finland	Preserved smock mill with sails and annular sail	late C20
FINMILL 01_06	Finland	Preserved open-trestle post mill with sails	late C20
FINMILL 01_07	Finland	Preserved smock mill with sails and tailpole	late C20
FINMILL 01_08	Finland	Preserved open-trestle post mill with sails	late C20
FINMILL 01_09	Finland	Preserved post mill with sails and trestle buried in stone substructure	late C20
FINMILL 01_10	Finland	Preserved six-sailed smock mill	late C20
FINMILL 01_11	Finland	Very small preserved hollow-post(?) mill above square wooden structure	late C20
FINMILL 01_12	Mediterranean region	Pair of stationary stone windmills, both with sails	late C20
FINMILL 01_13	Mediterranean region	Pair of stationary stone windmills, both with sails	late C20
FINMILL 01_14	Mediterranean region	Stationary stone windmill with jib sails typical of region	late C20
FINMILL 01_15	Mediterranean region	Preserved tower mill with conical cap and jib sails	late C20
HIGHSALV 01_01	Sussex: Keymer, Oldland Mill	Derelict post mill with two sails	c1980

HIGHSALV 01_02	Sussex: Barnham	View inside cap of tower mill showing brakewheel	late C20	
HIGHSALV 01_03	Sussex: Barnham	View from dust floor of tower mill showing lower half of brakewheel	late C20	
HIGHSALV 01_04	Sussex: Barnham	View of stone floor of tower mill showing two pairs of stones	late C20	
HIGHSALV 01_05	Sussex: Barnham	Interior of tower mill showing great spur wheel, secondary gear ring, stone nut and engine drive(?)	late C20	
HIGHSALV 01_06	Sussex: Barnham	Interior of tower mill showing great spur wheel, secondary gear ring, stone nut and other gearing	late C20	
HIGHSALV 01_07	Prob. Barnham, Sussex	Interior of granary/outbuilding	late C20	
HIGHSALV 01_08	Sussex: Keymer, Oldland Mill	Two men working on repairs to post mill; one is standing on lower sail, another on ladder	c1980	Shows people: man on ladder is John Annett, founder of project to restore mill
HIGHSALV 01_09	Sussex: Barnham	View inside cap of tower mill showing brakewheel	late C20 late 1970s	
HIGHSALV 01_10	Sussex: Durrington, High Salvington	View inside roundhouse of post mill under repair, showing main post	or early 1980s	
HIGHSALV 01_11	Unknown	Part of cap frame of tower mill showing reinforcing ironwork	late C20	
HIGHSALV 01_12	Unknown	Part of cap frame and curb of tower mill showing reinforcing ironwork	late C20	
HIGHSALV 01_13	Sussex: Durrington, High Salvington	Post mill under repair, with no sails and weatherboarding patched	1976-80	
HIGHSALV 01_14	Sussex: Shipley, King's Mill	Close-up of striking gear, part of sail and petticoat of cap of restored smock mill	late C20	
HIGHSALV 01_15	Sussex: Keymer, Oldland Mill	Derelict and sailless post mill supported by timber props	early 1980s	
HIGHSALV 01_16	Sussex: Keymer, Oldland Mill	Side view of derelict and sailless post mill supported by timber props	early 1980s	

HIGHSALV 01_17	Sussex: Shipley, King's Mill	Close-up of fantail, fan platform and winding wheel (or striking wheel?) of restored smock mill	late C20
HIGHSALV 01_18	Sussex: Shipley, King's Mill	Close-up of fantail, fan platform and winding wheel (or striking wheel?) of restored smock mill	late C20
HIGHSALV 01_19	Sussex: Shipley, King's Mill	Close-up of striking gear of restored smock mill	late C20
HIGHSALV 01_20	Unknown	New sails and cap frame of smock/tower mill being made up on ground	late C20
LINCSMIL 01_01	Yorkshire: Skidby	Mid-distant view of restored tower mill with sails	late C20
LINCSMIL 01_02	Yorkshire: Skidby	Looking up from ground at cap and sails of restored tower mill and showing engine drive pulley on tower wall	late C20
LINCSMIL 01_03	Yorkshire: Skidby	Restored tower mill with sails	late C20
LINCSMIL 01_04	Yorkshire: Skidby	Sails and upper part of tower of restored tower mill	late C20
LINCSMIL 01_05	Unknown	Piece of artwork showing Lincs-type tower mill and headed "The Survivors"	late C20
LINCSMIL 01_06	Yorkshire: Skidby	Looking up at cap, sails and upper tower of restored tower mill	late C20
LINCSMIL 01_07	Yorkshire: Skidby	Restored tower mill with sails	late C20
LINCSMIL 01_08	Yorkshire: Skidby	Restored tower mill with sails	late C20
LINCSMIL 01_09	Nottinghamshire: North Leverton	Tower mill in working order	19th July 1969
LINCSMIL 01_10	Lincolnshire: Boston, Maud Foster Mill	Upper part of preserved five-sailed tower mill, seen above roofs of houses	late C20
LINCSMIL 01_11	Lincolnshire: Long Sutton, Brunswick Mill	Derelict tower mill with brakewheel and six sails	c1970
LINCSMIL 01_12	Lincolnshire: Sibsey, Trader Mill	Derelict tower mill with four out of six sails	1960-70
LINCSMIL 01_13	Lincolnshire: Alford (Hoyle's) or Sibsey (Trader)	View looking up at cap and fan of preserved tower mill, showing also part of sail and striking chain with weight	1970s or 80s
LINCSMIL 01_14	Lincolnshire: Wrawby	Restored post mill with sails	c1970

LINCSMIL 01_15	Lincolnshire: Boston, Maud Foster Mill	Disused five-sailed tower mill with sails	1960-70
NEWCOMEN 01_01	Unknown	Lengths of timber stacked in workshop	Apr-73
NEWCOMEN 01_02	Unknown	Lengths of timber stacked in workshop	Apr-73
NEWCOMEN 01_03	Unknown	Wheel and section of surviving brickwork of derelict watermill	Apr-73
NEWCOMEN 01_04	Unknown	Wheel, axle and derelict brickwork of watermill	Apr-73
NEWCOMEN 01_05	Unknown	Remains of sluice gear of former watermill	Apr-73
NEWCOMEN 01_06	Unknown	Remains of sluice gear of former watermill	Apr-73
NEWCOMEN 01_07	Unknown	Remains of sluice gear and brickwork of former watermill	Apr-73
NEWCOMEN 01_08	Unknown	Remains of brickwork of former waterwheel	Apr-73
NEWCOMEN 01_09	Unknown	Bridge over river	Apr-73 Non-mill so could be returned to WADOAM
NEWCOMEN 01_10	Unknown	Bridge over river	Apr-73 Non-mill so could be returned to WADOAM
NEWCOMEN 01_11	Sussex: Nutley	Preserved post mill with sails	Apr-73
NEWCOMEN 01_12	Surrey: Capel, Shiremark Mill	View inside base of smock mill destroyed by fire, showing several items of iron shafting/gearing	Apr-73
NEWCOMEN 01_13	Surrey: Capel, Shiremark Mill	Surviving base and windshaft of smock mill destroyed by fire	Apr-73
NEWCOMEN 01_14	Surrey: Capel, Shiremark Mill	Wreckage and rubble inside base of former smock mill, showing wallower and part of windshaft	Apr-73
NEWCOMEN 01_15	Surrey: Capel, Shiremark Mill	Wreckage and rubble inside base of former smock mill, showing various items of gearing including stone nut and winding gear	Apr-73
NEWCOMEN 01_16	Surrey: Capel, Shiremark Mill	Tail of windshaft and striking rod of former smock mill	Apr-73
NEWCOMEN 01_17	Surrey: Capel, Shiremark Mill	Exterior view of surviving base of smock mill, showing windshaft also	Apr-73

NEWCOMEN 01_18	Unknown	Part of interior of unidentified timber structure	Apr-73
NEWCOMEN 01_19	Unknown	New sails for windmill being made up inside workshop	Apr-73
NEWCOMEN 01_20	Unknown	New sail for windmill being made up in workshop	Apr-73
NEWCOMEN 02_01	Unknown	Various people making up new sail for windmill on ground	Apr-73
NEWCOMEN 02_02	Unknown	Unidentified watermill buildings by bridge by river	Apr-73
NEWCOMEN 02_03	Devon?	Unidentified watermill building with wheel by river	Apr-73
NEWCOMEN 02_04	Devon?	Close-up of wheel of mill in previous image	Apr-73
NEWCOMEN 02_05	Bristol?	Preserved historic steamboat by river in what appears to be port	Apr-73
NEWCOMEN 02_06	Devon?	Close-up of wheel of mill in 02_03	Apr-73
NEWCOMEN 02_07	Unknown	Close-up of wheel and launder of unidentified watermill	Apr-73
NEWCOMEN 02_08	Unknown	Same image as 02_07	Apr-73
NEWCOMEN 02_09	Unknown	View of historic pumping engine inside waterworks	Apr-73
NEWCOMEN 02_10	Sussex: Heathfield, Punnett's Town, Blackdown/Cherry Clack Mill	Owner Archie Dallaway standing in doorway of roundel with his Windmill Certificate; part of smock and gallery visible	Apr-83
NEWCOMEN 02_11	Prob. Siddington, Gloucestershire	Castellated tower of tower mill	Apr-83
NEWCOMEN 02_12	Unknown	Unidentified item of machinery, consisting of iron gear ring plus structure resembling casing of turbine, in garden of house	Apr-83
NEWCOMEN 02_13	Unknown	Close-up of object in 02_11	Apr-83
NEWCOMEN 02_14	Unknown	Close-up of object in 02_12	Apr-83
NEWCOMEN 02_15	Sussex: Nutley	Restored open-trestle post mill with sails	Apr-83
NEWCOMEN 02_16	Sussex: Nutley	Restored open-trestle post mill with sails	Apr-83

NEWCOMEN 02_17	Prob. SE England	White weatherboarded watermill building with red tiled roof and large engine drive pulley on wall	Apr-83
NEWCOMEN 02_18	Prob. SE England	Close-up of white weatherboarded watermill building and wheel	Apr-83 Prob. same mill as 02_17
OLDLAND 01_01	Sussex: Keymer, Oldland Mill	Derelict post mill with two sails	c1980
OLDLAND 01_02	Sussex: Keymer, Oldland Mill	Derelict post mill with two sails	c1980
OLDLAND 01_03	Sussex: Keymer, Oldland Mill	Derelict post mill with two sails	c1980
OLDLAND 01_04	Sussex: Keymer, Oldland Mill	Derelict post mill with two sails	c1980
OLDLAND 01_05	Sussex: Keymer, Oldland Mill	Derelict post mill with two sails	c1980
OLDLAND 01_06	Sussex: Keymer, Oldland Mill	Derelict post mill with two sails	c1980
OLDLAND 01_07	Sussex: Durrington, High Salvington	Post mill under repair, with sails removed and body propped up with steel "legs"	c1976-80
OLDLAND 01_08	Sussex: Durrington, High Salvington	Post mill under repair, with sails removed and body propped up with steel "legs"	c1976-80
OLDLAND 01_09	Sussex: Keymer, Oldland Mill	Post mill under repair, with sails removed and body propped up with steel "legs"	c1980
OLDLAND 01_10	Sussex: Keymer, Oldland Mill	Post mill under repair, with sails removed and body propped up with steel "legs"	c1980
OLDLAND 01_11	Sussex: Keymer, Oldland Mill	Post mill under repair, with sails removed and body propped up with steel "legs"	C1980
OLDLAND 01_12	Lincolnshire: Sibsey, Trader Mill	6-sailed tower mill in working order	1980s or 90s
OLDLAND 01_13	Norfolk: Upton, Palmer's Mill	Restored hollow-post windpump with two sails fitted	1980s
OLDLAND 01_14	Walsoken, Norfolk(?)	Inscription on monument in church to Adam de Walsoken, with illustration of windmill	late C20
OLDLAND 01_15	Unknown	Carving of windmill on bench end in church	late C20
OLDLAND 01_16	Prob. Bourn or Great Gransden, Cambs	Open-trestle post mill in w/o, with common sails spread with canvas; man in foreground	late C19 or early C20
OLDLAND 01_17	Sussex: Heathfield, Punnett's Town, Blackdown/Cherry Clack Mill	Restored smock mill with sails	late C20

OLDLAND 01_18	Sussex: Heathfield, Punnett's Town, Blackdown/Cherry Clack Mill	Restored smock mill with sails	late C20
OLDLAND 01_19	Sussex: Clayton, "Jill" Mill	Derelict post mill with sails	pre-1979 pre-1907/8
OLDLAND 01_20	Sussex: Barcombe	Disused post mill without sails; man and child standing on ladder	(when mill burnt down)
SUSSEX 01_01	Sussex: Nutley	Open-trestle post mill under repair, showing new breast framing and roof removed to expose brake- and tailwheels; stocks still on Men working by substructure of post mill under repair, preparing to lift various	10th July 1971
SUSSEX 01_02	Sussex: Nutley	timbers into position	c1970
SUSSEX 01_03	Sussex: Nutley	Sunset view of restored open-trestle post mill with sails	1970s 1970s or
SUSSEX 01_04	Sussex: Nutley	Restored open-trestle post mill with sails Party of schoolchildren at mill, two of whom are pushing on the tailpole to turn the mill into the wind; trestle, ladder and part of body are visible	80s
SUSSEX 01_05	Sussex: Nutley	View of restored open trestle post mill showing group of children and adults on ladder and on ground beside mill	early 1970s
SUSSEX 01_06	Sussex: Nutley	View of restored post mill with sails showing Morris dancers and large crowd of spectators in foreground; Open Day?	late 1980s or 1990s
SUSSEX 01_07	Sussex: Durrington, High Salvington	Snow scene showing preserved post mill with dummy sails and concrete roundhouse	mid-late C20
SUSSEX 01_08	Sussex: Durrington, High Salvington		mid/late 1970s or
SUSSEX 01_09	Sussex: Polegate	Preserved tower mill with sails (fan missing)	1980s
SUSSEX 01_10	Sussex: Shipley, King's Mill	Smock mill scaffolded for repair, with cap on ground	c1990

SUSSEX 01_11	Sussex: Heathfield, Punnett's Town, Blackdown/Cherry Clack Mill	View of preserved smock mill showing damage caused to sails and weatherboarding by lightning strike	c1980	
SUSSEX 01_12	Sussex: Heathfield, Punnett's Town, Blackdown/Cherry Clack Mill	Preserved smock mill with sails	early 1970s	
SUSSEX 01_13	Sussex: Polegate	View of interior of milling museum showing model post mill, various gearwheels, display cases and other items	late C20	
SUSSEX 01_14	Sussex: Boxgrove, Halnaker	Preserved tower mill with dummy sails	1970s	
SUSSEX 01_15	Sussex: Herstmonceux, Windmill Hill	Derelict post mill without sails	20th February 1968	
SUSSEX 01_16	Sussex: Westham, Stone Cross	Preserved tower mill with two sails; ladder leaning against tower suggests repairs in progress	29th April 1967	
SUSSEX 01_17	Sussex: Durrington, High Salvington	Post mill under repair, with sails removed and body propped up with steel "legs"	c1976-80	
SUSSEX 01_18	Unknown	Two men working on new brakewheel or great spur wheel of windmill in workshop	late C20	
SUSSEX 01_19	Sussex: Polegate	Tower mill in w/o	early to mid-C20	
SUSSEX 01_20	Sussex: Eastbourne, Black Mill	Painting showing post mill in w/o but heavily tailsick; sea in background	C19	The rural scene the painting depicts is idealised, but the mill itself is authentic judging by photo of it in Towner Hall Museum, Eastbourne
SUSSEX 02_01	Sussex: Eastbourne, Ocklynge	View of archaeological site showing what appears to be "cross" in ground for substructure of sunk post mill	4th June 1970	
SUSSEX 02_02	Unknown	View of archaeological site showing remains of walls of brick and flint building - former mill?	late C20	

SUSSEX 02_03	Sussex: Icklesham, Hog Hill	Mid-distant view of preserved post mill with sails	27th June 1969	
SUSSEX 02_04	Sussex: Icklesham, Hog Hill	Mid-distant view of preserved post mill with sails	27th June 1969	
SUSSEX 02_05	Sussex: Friston	Mid-distant view of derelict post mill with sails	early C20	
SUSSEX 02_06	Sussex: probably Eastbourne (Ocklynge) or Arun Mill, Littlehampton	Derelict tower mill, with brakewheel and one sail, falling after being blown up with explosives	early C20	
SUSSEX 02_07	Sussex: Friston	Post mill in w/o, with miller and wife(?) in doorway and period car in foreground	early C20	
SUSSEX 02_08	Sussex: Friston	Derelict post mill with sails; body partially collapsed	early C20 pre-1885	
SUSSEX 02_09	Sussex: Lewes, Spital Hill Mill	Blurred view of open-trestle post mill, apparently in w/o, on hill with other buildings	when mill burnt	
SUSSEX 02_10	Sussex: Lewes, Southern (Cheale's) post mill	Sunken portion of post mill roundhouse in use as swimming pool; base of Pipes Passage smock mill visible in background	11th June 1968	
SUSSEX 02_11	Sussex: Lewes, Southern (Cheale's) post mill	Post mill in w/o, with Smart's smock mill visible in background in distance	late C19 or early C20	Note on photo wrongly identifies it as "Kingston Mill, Lewes"
SUSSEX 02_12	Sussex: Seaford, Sutton Mill	Derelict post mill with stocks and carriage for tailpole fan	late C19 or early C20	
SUSSEX 02_13	Sussex: Barnham	Tower mill with cap, scaffolded for repairs	1990s	
SUSSEX 02_14	Sussex: Kingston, Ashcombe Mill	Artificially tinted postcard of six-sailed post mill in w/o	late C19 or early C20	
SUSSEX 02_15	Sussex: Lewes, Pipes Passage	House-converted surviving base of smock mill	11th June 1968 pre-1891 (when mill demolished)	
SUSSEX 02_16	Sussex: Kingston, "Old Duck" smock mill	Derelict smock mill with cap and sails		
SUSSEX 02_17	Sussex: Earnley	Partially restored smock mill without cap or sails	c1990	

SUSSEX 02_18	Sussex: Earnley	Smock mill under repair, with cap and two sails; weatherboarding in course of replacement	c1976	Appears in "Windmills n Sussex" by A Foord Hughes
SUSSEX 02_19	Sussex: Singleton, Weald and Downland Open-Air Museum	Reconstructed hollow-post windpump from Pevensey Marshes, Westham	late C20	
SUSSEX 02_20	Sussex: Keymer, Oldland Mill	Watercolour of post mill in w/o	early C20	
SUSSEX 03_01	Sussex: Keymer, Oldland Mill	Post mill under reconstruction with windshaft, tailwheel and main timbers of new body in place	mid-1990s	
SUSSEX 03_02	Sussex: Keymer, Oldland Mill	New timber components on ground at mill site, ready for installation	mid-1990s	
SUSSEX 03_03	Sussex: Keymer, Oldland Mill	Mill in same condition as in 03_01; men working nearby	mid-1990s	
SUSSEX 03_04	Sussex: Keymer, Oldland Mill	View of post mill under reconstruction, with post, crowntree, sheers, windshaft and upper side rails in place	mid-1990s	
SUSSEX 03_05	Sussex: Keymer, Oldland Mill	Close-up of exposed windshaft and tailwheel of post mill under reconstruction	mid-1990s	
SUSSEX 03_06	Sussex: Keymer, Oldland Mill	Mill in similar condition to that shown in 03_05, with men at work lifting new breast frame into place	mid-1990s	
SUSSEX 03_07	Sussex: Keymer, Oldland Mill	New breast frame being made up into workshop	mid-1990s	
SUSSEX 03_08	Sussex: Keymer, Oldland Mill	New side frame being made up on ground	mid-1990s	
SUSSEX 03_09	Sussex: Keymer, Oldland Mill	Various timber components being made up on trestles in mill field	mid-1990s	
SUSSEX 03_10	Sussex: Keymer, Oldland Mill	New side girt(?) in workshop	mid-1990s	
SUSSEX 03_11	Sussex: Keymer, Oldland Mill	Derelict post mill with no sails and body propped; man working on part of new buck frame in foreground	mid-1990s	
SUSSEX 03_12	Sussex: Keymer, Oldland Mill	Derelict post mill without sails and body propped; unidentified man in foreground	mid-1990s	

SUSSEX 03_13	Sussex: Keymer, Oldland Mill	Derelict post mill without sails and body propped	mid-1990s
SUSSEX 03_14	Sussex: Keymer, Oldland Mill	Quarterbar/crosstree joint	late C20
SUSSEX 03_15	Sussex: Keymer, Oldland Mill	View of bin floor showing sack hoist	1960
SUSSEX 03_16	Sussex: Keymer, Oldland Mill	Derelict post mill with two sails	late C20
SUSSEX 03_17	Sussex: Keymer, Oldland Mill	Coloured painting of post mill with two sails	Painting signed "Raymond 1974 Duthy Wed 28th 1974"
SUSSEX 03_18	Sussex: Keymer, Oldland Mill	Interior of post mill under reconstruction, showing detail of framing	1990s
SUSSEX 03_19	Sussex: Mayfield, Argos Hill Mill	Preserved post mill with sails	1970s
SUSSEX 03_20	Sussex: Clayton, "Jill" Mill	Preserved post mill with sails and fantail	c1984
SUSSEX 04_01	Sussex: Clayton, "Jill" Mill	Men working on raising new fan carriage and wheels into position	c1983
SUSSEX 04_02	Sussex: Clayton, "Jill" Mill	Post mill under repair with men on scaffolding repainting it; stocks in position	c1980
SUSSEX 04_03	Sussex: Clayton, "Jill" Mill	Interior view of preserved post mill showing side framing	late C20
SUSSEX 04_04	Sussex: Clayton, "Jill" Mill	Interior view of preserved post mill showing brake- or tailwheel, one pair of stones and machine drive	late C20
SUSSEX 04_05	Sussex: Clayton, "Jill" Mill	New sails being made up on ground	early 1980s
SUSSEX 04_06	Sussex: Clayton, "Jack" and "Jill" mills	Downland scene with preserved post mill and tower mill, both with sails	late C20
SUSSEX 04_07	Sussex: Falmer, Race Hill Mill	Derelict post mill with sails and tailpole fan	late C19 or early C20
SUSSEX 04_08	Sussex: Brighton, Cuttress' Mill, Rose Hill	Tower mill in w/o	late C19 or early C20
SUSSEX 04_09	Sussex: West Blatchington	Preserved smock mill floodlit and with sails dressed with bunting	late C20
SUSSEX 04_10	Sussex: West Blatchington	Photo of diagram showing workings of mill	late 1970s
SUSSEX 04_11	Sussex: West Blatchington	Preserved smock mill with sails	1970s
SUSSEX 04_12	Denmark: Funen, Ullerslev	Modern wind turbine with 3-bladed "propellor" and fantail on cabin	late C20

SUSSEX 04_13	Denmark	Modern concrete wind turbine with fantail and 2-bladed propellor	1970s	
SUSSEX 04_14	Sussex: Shipley, King's Mill	Preserved smock mill with sails	late C20	
SUSSEX 04_15	Surrey: Outwood	Post mill in w/o, sails apparently turning	late C20	
SUSSEX 04_16	Suffolk: Herringfleet	Preserved smock drainage mill, with sails spread with canvas and turning	late C20	
SUSSEX 04_17	Sussex: Shipley, King's Mill	Meal bin in unidentified windmill or watermill	late C20	
SUSSEX 04_18	Sussex: Chailey, North Common	Preserved smock mill with sails	late C20	
SUSSEX 04_19	Unknown	Very good model post mill with roundhouse cut away to show trestle	late C20	
SUSSEX 04_20	Kent: Rolvenden	Preserved post mill with sails	late C20	
SUSSEX 05_01	Sussex: Heathfield, Punnett's Town, Blackdown/Cherry Clack Mill	Preserved smock mill with sails	1970s	
SUSSEX 05_02	Sussex: Heathfield, Punnett's Town, Blackdown/Cherry Clack Mill	Archie Dallaway on scaffolding working on repairs to mill following lightning strike	c1980	
SUSSEX 05_03	Sussex: Bexhill, Downs or Hoad's Mill	Post, trestle and roundhouse of collapsed post mill, surrounded by wreckage of body, amid which one millstone is visible	1960-70	
SUSSEX 05_04	Sussex: Mayfield, Argos Hill Mill	Preserved post mill with sails	1970s 9th November	
SUSSEX 05_05	Sussex: Icklesham, Hog Hill	Preserved post mill with sails	1968	
SUSSEX 05_06	Sussex: Ringmer, Glyndebourne Mill	Post mill in w/o	c1910	Dating is Brunnarius'
SUSSEX 05_07	Sussex: Lewes, Malling or Southern Mill	Distant view of post mill with sails and apparently in working order, against Downland landscape	late C19 or early C20	Note on photo largely cut off: ".....mill.....Lewes"
SUSSEX 05_08	Sussex: Lewes, Smart's or Shelley's Mill	Smock mill in w/o, with two men standing on stage	late C19 or early C20	
SUSSEX 05_09	Sussex: Nutley	Preserved open-trestle post mill with sails	1970s or 80s	
SUSSEX 05_10	Sussex: Seaford, Sutton Mill	View of very fine post mill in working order with sails and tailpole fan	late C19 or early C20	
SUSSEX 05_11	Sussex: East Blatchington	Tower windpump wth cap and cross for sails	late C19 or early C20	

SUSSEX 05_12	Sussex: East Blatchington	Rough watercolour(?) showing post mill, with sails beside farm buildings: unidentified structure on roof	?	
SUSSEX 05_13	Sussex: Bishopstone	Painting depicting windmill and tide mills	C19	
SUSSEX 05_14	Unknown	Rather striking painting of smock mill in working order, by sea	?	Looks like Short's Mill, Walberton, but setting doesn't match
SUSSEX 05_15	Prob. Sussex	Wreckage of post mill after collapse/demolition, showing crowntree and upper part of main post	late C19 or early C20	
SUSSEX 05_16	Sussex: Rodmell	Derelict post mill with stocks and two damaged sails	late C19 or early C20	
SUSSEX 05_17	Sussex: Shipley, King's Mill	Preserved smock mill with sails	late C20	
SUSSEX 05_18	France: Beauce region	Preserved post mill with sails	c1975	
SUSSEX 05_19	France: Beauce region, Talcy	Buck frame and trestle of partially reconstructed post mill	c1975	
SUSSEX 05_20	Sussex: Heathfield, Punnett's Town, Blackdown/Cherry Clack Mill	Preserved smock mill with cap (sails and fan not yet fitted)	c1970	
WATERMILL 01_01	Unknown	Interior of watermill showing pit wheel, upright shaft, wallower and other gearwheel	late C20	
WATERMILL 01_02	Unknown	Part of derelict watermill building with wheel	late C20	Wheel wider than it is high
WATERMILL 01_03	Unknown	Preserved watermill building and mill race	late C20	
WATERMILL 01_04	Unknown	Photo of 1910 blurb of William Garner & Sons of Mark Lane, London, millers and millwrights, with illustrations of some of their millstones and other products	1910	
WATERMILL 01_05	Unknown	Group of people standing outside preserved watermill building	late C20	
WATERMILL 01_06	Unknown	Preserved watermill building by river, with very tall chimney nearby	late C20	
WATERMILL 01_07	Unknown	Close-up of watermill building seen in 01_06	late C20	
WATERMILL 01_08	Unknown	Interior of watermill building showing part of wheel	late C20	

WATERMILL 01_09	Unknown	Part of watermill building showing top of wheel	late C20	
WATERMILL 01_10	Unknown	Interior of watermill showing pit wheel, upright shaft and great spur wheel	late C20	
WATERMILL 01_11	Unknown	Interior of watermill showing two large iron gearwheels	late C20	
WATERMILL 01_12	Unknown	Interior of watermill, probably that shown in 01_10, showing pit wheel, great spur wheel, stone nut, quant and belt drum	late C20	
WATERMILL 01_13	Unknown	Exterior view of large watermill building	late C20	
WATERMILL 01_14	Greater London: Keston, nr Bromley	Internal view of post mill showing main post, crowntree, great spur wheel and stone nut	late C20	
WATERMILL 01_15	Greater London: Keston, nr Bromley	Internal view of post mill showing brakewheel, wallower, upright shaft, governors and two pairs of stones in breast	late C20	Note belt drum on u/s
WATERMILL 01_16	Greater London: Keston, nr Bromley	Interior of post mill showing bolter/wire machine	late C20	
WATERMILL 01_17	Greater London: Keston, nr Bromley	Interior of post mill showing spouts ad jog scry	late C20	
WATERMILL 01_18	Greater London: Keston, nr Bromley	Interior of post mill showing machine drive	late C20	
WATERMILL 01_19	Greater London: Keston, nr Bromley	View inside post mill roundhouse showing main post and quarterbars	late C20	
WESTBLATCH 01_01	Sussex: West Blatchington	Smock mill under repair with stocks on ground	c1980	
WESTBLATCH 01_02	Sussex: West Blatchington	Smock mill under repair, with sails removed; man being carried by crane towards cross	c1980	
WESTBLATCH 01_03	Sussex: West Blatchington	Smock mill under repair, with sails removed; man being lowered by crane onto cross	c1980	
WESTBLATCH 01_04	Sussex: West Blatchington	Smock mill under repair, with stocks being placed in position by crane	c1980	

WESTBLATCH 01_05	Sussex: West Blatchington	Smock mill under repair, with stocks being placed in position by crane	c1980	
WESTBLATCH 01_06	Sussex: West Blatchington	Smock mill under repair, with stocks being placed in position by crane	c1980	
WESTBLATCH 01_07	Sussex: West Blatchington	Smock mill under repair, with stocks being placed in position by crane	c1980	
WESTBLATCH 01_08	Unknown	Framed piece of cloth with illustration of smock/tower mill	late C20?	
WESTBLATCH 01_09	Sussex: West Blatchington	Smock mill without sails and scaffolded for repair	c1980	
WESTBLATCH 01_10	Sussex: West Blatchington	Smock mill scaffolded for repair, with sails still on	c1980	
WESTBLATCH 01_11	Sussex: West Blatchington	Smock mill scaffolded for repair, with sails still on; men working on scaffolding	c1980	
WESTBLATCH 01_12	Sussex: West Blatchington	Close-up of cross showing stumps of stocks, one damaged	c1980	
WESTBLATCH 01_13	Sussex: West Blatchington	Smock mill scaffolded for repair, with sails removed	c1980	
WESTBLATCH 01_14	Sussex: Washington	Village sign with representation of smock mill	late C20	
WESTBLATCH 01_15	Sussex: West Blatchington	Smock mill under repair, with sail frames being placed in position by crane	c1980	
WESTBLATCH 01_16	Sussex: West Blatchington	Sail frames being placed in position by crane; man working on one of them	c1980	
WESTBLATCH 01_17	Sussex: West Blatchington	Sail frames being placed in position by crane; man working on one of them	c1980	
WESTBLATCH 01_18	Sussex: West Blatchington	Sail frames being placed in position by crane; man working on one of them	c1980	
WESTBLATCH 01_19	Sussex: Clayton, "Jill" Mill	Side view of post mill scaffolded for repair, with stocks still on	c1980	
WELSHMIL 01_01	Unknown	Unidentified historic agricultural machine standing on concrete supports within field; scene possibly a steam fair?	late C20	Non-mill so return to Singleton?
WELSHMIL 01_02	Unknown	Unidentified historic agricultural machine standing on concrete supports within field; scene possibly a steam fair?	late C20	Non-mill so return to Singleton?

WELSHMIL 01_03	Wales?	Exterior of watermill building with wheel	late C20	
WELSHMIL 01_04	Wales?	Close-up of wheel of mill in 01_03	late C20	
WELSHMIL 01_05	Wales?	Close-up of wheel of mill in 01_04	late C20	
WELSHMIL 01_06	Wales?	Large watermill building with wheel scaffolded for repairs	late C20	
WELSHMIL 01_07	Wales?	Exterior view of watermill building with wheel	late C20	
WELSHMIL 01_08	Wales?	Exterior view of watermill building, apparently partly in use as house	late C20	
WELSHMIL 01_09	Wales?	Derelict and overgrown wheel and launder of watermill	late C20	
WELSHMIL 01_10	Wales?	Exterior view of large watermill building by stream, with group of visitors	late C20	
WELSHMIL 01_11	Wales?	Exterior view of watermill building with large overshot wheel and launder	late C20	
WELSHMIL 01_12	Wales?	Grotty old bit of cloth on ground	late C20	
WELSHMIL 01_13	Cheshire?	Large half-timbered Tudor house, possibly Little Moreton Hall, Cheshire	late C20	
WELSHMIL 01_14	Wales?	Exterior view of part brick, part stone watermill building by stream	late C20	
WELSHMIL 01_15	Wales?	Exterior view of preserved watermill building by stream	late C20	
WELSHMIL 01_16	Wales?	Exterior view of watermill building with sluice gates	late C20	
WELSHMIL 01_17	Wales?	Interior view of watermill showing sack hoist (?) and wooden supporting columns	late C20	
WELSHMIL 01_18	Wales?	Exterior view of stone watermill building with derelict granary(?) built on; group of visitors outside	late C20	These photos probably taken on an SPAB mill tour
WELSHMIL 01_19	Wales?	Exterior view of watermill building by what appears to be narrow-gauge railway, with visitors outside	late C20	
WELSHMIL 01_20	Wales?	Exterior view of large half-timbered building, part of which is presumably watermill	late C20	
WELSHMIL 02_01	Wales?	Unidentified man, presumably a miller	late C20	

WELSHMIL 02_02	Wales?	Part of watermill building showing derelict wooden wheel with collapsed iron gear ring	late C20
WELSHMIL 02_03	Wales?	View of watermill building by road	late C20
WELSHMIL 02_04	Wales?	Part of watermill building apparently converted to house	late C20
WELSHMIL 02_05	Wales?	View of mill shown in 02_04	late C20
WELSHMIL 02_06	Prob. Bickerstaffe, Lancashire	Tower of tower mill converted to house with conical roof	late C20
WELSHMIL 02_07	Prob. Burscough, Lancashire	Derelict tower of tower mill	late C20
WELSHMIL 02_08	Lancashire: Bretherton	House-converted tower mill with dummy cap and cross	late C20
WELSHMIL 02_09	Captioned "St Stephens"	Large iron waterwheel with crankshaft attachment, apparently standing alone in field	late C20
WELSHMIL 02_10	Captioned "Hunworth"	View of unidentified watermill building	late C20
WELSHMIL 02_11	Unknown	Memorial stone to Thomas Newcomen, with plaque on which is diagram of workings of steam engine	late C20
WELSHMIL 02_12	Unknown	Interior view of watermill showing various items of machinery and timberwork plus curious circular stone structure	late C20
WELSHMIL 02_13	Captioned "Cockhaise"	Stone tablet in wall to Francis Wyatt, dated 1697	late C20
WELSHMIL 02_14		Interior view of watermill showing large wooden waterwheel	late C20
WELSHMIL 02_15	Captioned "Helston Museum"	Museum section of mill showing two large wooden gearwheels, one with gear ring on its shaft	late C20
WIND 01_01	Norfolk: Wicklewood	Tower mill under restoration, with cap and fantail; man being carried towards cap on cradle by crane	C1980
WIND 01_02	Norfolk: Wicklewood	Tower mill under restoration, with cap and fantail; man being carried towards cap on cradle by crane	c1980

WIND 01_03	Norfolk: Wicklewood	Tower mill under restoration, with cap and fantail; man being carried towards cap on cradle by crane	c1980
WIND 01_04	Norfolk: Wicklewood	Tower mill under restoration, with cap and fantail; man being carried towards cap on cradle by crane	c1980
WIND 01_05	Norfolk: Wicklewood	Tower mill under restoration, with cap and fantail; man being carried towards cap on cradle by crane	c1980
WIND 01_06	Norfolk: Wicklewood	Tower mill under restoration, with cap and fantail; man being carried towards cap on cradle by crane	c1980
WIND 01_07	Norfolk: Wicklewood	Tower mill under restoration, with cap and fantail; man being carried towards cap on cradle by crane	c1980
WIND 01_08	Norfolk: Wicklewood	Tower mill under restoration, with cap and fantail; man being carried towards cap on cradle by crane	c1980
WIND 01_09	Norfolk: Wicklewood	Tower mill under restoration, with cap; shadow on wall of man being carried towards cap on cradle by crane	c1980
WIND 01_10	Norfolk: Carbrooke	Tower of tower mill preserved with platform on top supporting wind generator	c1980
WIND 01_11	Norfolk: Carbrooke	Close-up view of wind generator on top of tower mill	c1980
WIND 01_12	Norfolk: prob. Honingham	Tower of tower mill scaffolded for house conversion	c1980
WIND 01_13	Suffolk: Great Thurlow	Preserved smock mill with sails	c1980
WIND 01_14	Suffolk: Great Thurlow	Preserved smock mill with sails	c1980
WIND 01_15	Unknown	Section of internal framing of watermill or post/smock mill, showing new timberwork	late C20
WIND 01_16	Unknown	Section of stone floor of wind- or watermill, showing part of one pair of stones	late C20

WIND 01_17	Sussex: Nutley	Sunset view of restored open-trestle post mill with sails	late C20 pre-1974 when sails fitted to tower mill	
WIND 01_18	Sussex: Clayton, Jack and Jill mills	Snow scene showing preserved post mill and tower mill, both with sails		
WIND 01_19	Leicestershire: Kibworth Harcourt	Preserved post mill with sails (rear ladder missing)	1960s	
WIND 01_20	Leicestershire: Kibworth Harcourt	Preserved post mill with sails (rear ladder missing)	1960s	
WIND 02_01	Sussex: Winchelsea, St Leonards' Mill	Derelict post mill without sails	1960s or 70s	
WIND 02_02	Sussex: Winchelsea, St Leonards' Mill	Derelict post mill without sails, showing right leaning of body	1960s or 70s	
WIND 02_03	Sussex: Winchelsea, St Leonards' Mill	Close-up of roundhouse of derelict post mill showing brick piers projecting through wall (or buttresses)	1960s or 70s	
WIND 02_04	Sussex: Winchelsea, St Leonards' Mill	Derelict post mill without sails, showing damage to boarding of front roof gable	1960s or 70s	
WIND 02_05	Sussex: Winchelsea, St Leonards' Mill	Derelict post mill without sails	1960s or 70s	
WIND 02_06	Sussex: Winchelsea, St Leonards' Mill	View of derelict post mill showing wheels of former drive from roof-mounted fan at bottom of rear ladder	1960s or 70s	
WIND 02_07	Sussex: Clayton "Jill" post mill	Preserved post mill with sails, scaffolded for repair/repainting	1970s	
WIND 02_08	Sussex: Clayton, "Jill" Mill	Preserved post mill with sails, scaffolded for repair/repainting	1970s	
WIND 02_09	Unknown	Painting showing post mill with farmer, plough and team of horses in foreground	?	Portrait entitled "Spring Ploughing"
WIND 02_10	Prob. Sussex	Painting by Constable showing Downland(?) scene with smock/tower mill apparently in w/o	C19	Portrait entitled "Windmill Among Houses With Rainbow"
WIND 02_11	Buckinghamshire: Ivinghoe, Pitstone Green	Preserved post mill with sails	prob. 1970s	

WIND 02_12	Buckinghamshire: Ivinghoe, Pitstone Green	Close-up of sails and front of buck of preserved post mill	prob. 1970s
WIND 02_13	Sussex: Pulborough, Nutbourne	Derelict tower mill with cap frame and stocks lying across top of tower	1970s
WIND 02_14	Sussex: Pulborough, Nutbourne	Looking up from ground at remains of fantail sheers and cogs of rack of derelict tower mill	1970s
WIND 02_15	Sussex: Pulborough, Nutbourne	Derelict tower mill with cap frame and stocks lying across top of tower	1970s
WIND 02_16	Sussex: Waldron, Cross-in-Hand	Post mill following storm damage with damaged sail hanging down	1969
WIND 02_17	Republic of Ireland: Tacumshane	Preserved tower mill with sails, thatched cap, bowsprit and tailpole	late C20
WIND 02_18	Republic of Ireland: Tacumshane	Preserved tower mill with sails, thatched cap, bowsprit and tailpole	late C20
WIND 02_19	Republic of Ireland: Tacumshane	Preserved tower mill with sails, thatched cap, bowsprit and tailpole	late C20
WIND 02_20	Republic of Ireland: Tacumshane	Preserved tower mill with sails, thatched cap, bowsprit and tailpole	late C20
WIND 03_01	Hampshire: Portsmouth, Dock Mill	Artificially coloured postcard showing tower mill, no longer working by wind but with cap and sails, with chimney and other buildings of associated business; children in costume of the era in foreground	late C19 or early C20
WIND 03_02	Buckinghamshire: Lacey Green	Derelict smock mill with one sail	c1970
WIND 03_03	Leicestershire: Shepshed	House-converted tower mill with cap, fantail and two sails	1960s or 70s
WIND 03_04	Kent: Rolvenden	Preserved post mill with sails	7th June 1957
WIND 03_05	Lincolnshire: Sibsey, Trader Mill	Tower mill under repair with cap roof off, exposing windshaft and brakewheel, and new sails on ground awaiting fitting	c1970
WIND 03_06	Belgium: Damme	Preserved tower mill with tailpole and sails, on mound by river	13th May 1957

WIND 03_07	Norfolk: Stalham, Hunsett Mill	Preserved tower windpump with sails	1960s or 70s
WIND 03_08	Suffolk: Herringfleet	Close-up of common sails (canvas unfurled) of restored smock drainage mill	1960s or 70s
WIND 03_09	Wiltshire: Wilton (nr Great Bedwyn)	Derelict tower mill with cap and part of one sail	1st November 1959
WIND 03_10	Norfolk: Tottenhill	Derelict post mill with two sails, leaning badly following storm damage	1960
WIND 03_11	Norfolk: Tottenhill	Derelict and partially collapsed post mill, with remains of one sail visible	1961
WIND 03_12	Greater London: Brixton	View of restoration of tower mill showing men working on fitting of new sail	c1964
WIND 03_13	Suffolk: Saxtead Green	Preserved post mill with stocks and two sail frames	1960s 12th April 1959
WIND 03_14	Essex: Ingatestone, Mill Green	Preserved post mill with sails	
WIND 03_15	Kent: Cranbrook, Union Mill	Smock mill under repair, showing large crowd watching fitting of new Dutch-type steel stocks	1960
WIND 03_16	Hertfordshire: Cromer	Post mill under repair, showing newly-restored buck; no sails or fan as yet	19th April 1968
WIND 03_17	Finland/Eastern Europe	Very small post/hollow-post mill with sails, apparently preserved; substructure buried within stone "roundhouse"	late C20
WIND 03_18	Finland/Eastern Europe	Preserved 6-sailed post/hollow-post mill, site probably open-air museum	late C20
WIND 03_19	Finland/Eastern Europe	Very small thatched post/hollow-post mill in open-air museum	late C20
WIND 03_20	Lincolnshire: Friskney	Carving of windmill on tombstone	late C20
WIND 04_01	Iran	Complex of horizontal windmills	late C20
WIND 04_02	Oxfordshire: Chinnor	Very derelict post mill in near-skeleton condition, with interior exposed; one sail remaining	1960-67
WIND 04_03	Greater London: Brixton	View of restoration of tower mill showing men working on fitting of new sail	c1964

WIND 04_04	Aden	Mid-distant view of two tower mills one six-sailed and one eight-sailed, and both apparently in w/o	late C20	Not clear if photo taken after fitting of new trestle
WIND 04_05	Norfolk: Garboldisham	Derelict post mill with two sails and body propped at front	c1971	
WIND 04_06	France: (Brittany?), Endevoan, Narbon Mill	Preserved tower mill with sails	1970s	
WIND 04_07	Lincolnshire: Stallingborough	Tower mill in w/o	1950s	
WIND 04_08	Nottinghamshire: North Leverton	Tower mill in w/o (cap boarding slightly damaged)	1950s or 60s	
WIND 04_09	Lincolnshire: Heapham	Windshaft, brake- and tailwheel of post mill at Laughterton, Lincs, on ground	1950s or 60s	
WIND 04_10	Cambridgeshire: Bourn	Preserved open-trestle post mill with sails	1950s or 60s	
WIND 04_11	Hampshire: Langstone	House-converted tower of tower mill with conical roof and "observation room" on top	1950s or 60s	
WIND 04_12	Lincolnshire: Burgh-le-Marsh, Dobson's Mill	Five-sailed tower mill in w/o	1950s or 60s	
WIND 04_13	Lincolnshire: Waltham	Tower mill in w/o with 4/6 sails	late 1950s or early 1960s	
WIND 04_14	Buckinghamshire: Brill, Nixey's Mill	Preserved post mill (boarding in need of repair) with sails	5th June 1964	
WIND 04_15	Somerset: Weare	House-converted tower of tower mill with look-out gallery on top	8th Sept 1957	Captioned "Badgeworth"
WIND 04_16	Lincolnshire: Heckington	Preserved eight-sailed tower mill	1950s or 60s	
WIND 04_17	Austria/Eastern Europe	Preserved tower mill with sails, conical cap and tailpole	late C20	
WIND 04_18	Foreign	Very small square post/hollow-post mill with sails, in field	late C20	
WIND 04_19	Prob. Tes, Hungary	Small six-sailed tower mill of primitive design	late C20	See photo in "Watermills and Windmills" by John Reynolds
WIND 04_20	Austria/Eastern Europe	Model in museum of six-sailed tower mill, cut away to show internal workings	late C20	