



Above, below and far below:

The UNION WINDMILL
on postcards and photographs
in the late 1930's and 40's.

4 Cap + Smock Jamies
CRSD?
Houses a joint are different.

Jan 19 44
Chimney pulled down in 1944



Above:
Repairs being carried out to the smock.



Cap unpainted
2 groups unsifted
or is the lower one and in so
sifters do not show?

possible wartime photo
or early 1950s

UNIO-01-67-02